



## Airworthiness Directive

**AD No.:** 2020-0007

**Issued:** 15 January 2020

Note: This Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EU) 2018/1139 on behalf of the European Union, its Member States and of the European third countries that participate in the activities of EASA under Article 129 of that Regulation.

This AD is issued in accordance with Regulation (EU) 748/2012, Part 21.A.3B. In accordance with Regulation (EU) 1321/2014 Annex I, Part M.A.301, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD, unless otherwise specified by the Agency [Regulation (EU) 1321/2014 Annex I, Part M.A.303] or agreed with the Authority of the State of Registry [Regulation (EU) 2018/1139, Article 71 exemption].

### Design Approval Holder's Name:

CFM INTERNATIONAL S.A.

### Type/Model designation(s):

CFM56-5B, CFM56-5C and CFM56-7B engines

**Effective Date:** 29 January 2020

**TCDS Number(s):** EASA.E.003 and EASA.E.004

**Foreign AD:** Not applicable

**Supersedure:** This AD supersedes EASA AD 2019-0150 dated 28 June 2019.

## ATA 72 – Engine – Rotating Air High Pressure Turbine Front Seal – Replacement

---

### Manufacturer(s):

SAFRAN Aircraft Engines, formerly SNECMA (France); General Electric Aircraft Engines (United States)

### Applicability:

CFM56-5B1, CFM56-5B2, CFM56-5B4, CFM56-5B5, CFM56-5B6, CFM56-5B7, CFM56-5B1/P, CFM56-5B2/P, CFM56-5B3/P, CFM56-5B4/P, CFM56-5B5/P, CFM56-5B6/P, CFM56-5B7/P, CFM56-5B8/P, CFM56-5B9/P, CFM56-5B3/P1, CFM56-5B4/P1, CFM56-5B1/2P, CFM56-5B2/2P, CFM56-5B3/2P, CFM56-5B4/2P, CFM56-5B6/2P, CFM56-5B9/2P, CFM56-5B3/2P1 and CFM56-5B4/2P1 engines, all serial numbers (s/n);

CFM56-5C2, CFM56-5C2/4, CFM56-5C2/F, CFM56-5C2/F4, CFM56-5C2/G, CFM56-5C2/G4, CFM56-5C2/P, CFM56-5C3/F, CFM56-5C3/F4, CFM56-5C3/G, CFM56-5C3/G4, CFM56-5C3/P, CFM56-5C4, CFM56-5C4/1, CFM56-5C4/P and CFM56-5C4/1P engines, all s/n; and

CFM56-7B20, CFM56-7B22, CFM56-7B24, CFM56-7B26, CFM56-7B27, CFM56-7B22/B1, CFM56-7B24/B1, CFM56-7B26/B1, CFM56-7B26/B2, CFM56-7B27/B1, CFM56-7B27/B3, CFM56-7B20/2, CFM56-7B22/2, CFM56-7B24/2, CFM56-7B26/2, CFM56-7B27/2 and CFM56-7B27A engines, all s/n.



These engines are known to be installed on, but not limited to, Airbus A318, A319, A320, A321 and A340 aeroplanes, and Boeing 737-600, 737-700, 737-800 and 737-900 aeroplanes.

### Definitions:

For the purpose of this AD, the following definitions apply:

**The applicable S/B:** CFM International CFM56-5B Service Bulletin (S/B) 72-1074, CFM56-5C S/B 72-0794 and CFM56-7B S/B 72-1042, as applicable.

**Affected part:** Rotating air high pressure turbine (HPT) front seals, having part number (P/N) 1795M36P01 or P/N 1795M36P02, and having a s/n as identified in Appendix 1 (P/N 1795M36P01) or Appendix 2 (P/N 1795M36P02) of this AD, except those for which one of the conditions (a) or (b) below applies:

- (a) The HPT front seal is new (not previously installed on an engine), or
- (b) The HPT front seal has never been removed from its original HPT disk and re-installed onto a different HPT disk.

**Serviceable part:** Any rotating air HPT front seal that is not an affected part.

### Groups:

Group 1 engines are those that have an affected part installed.

- Subgroup 1A are: CFM56-5B and CFM56-7B engines, having an affected part that, following re-installation, has never been operated on a CFM56-5C engine.
- Subgroup 1B are CFM56-5B and CFM56-7B engines, having an affected part that, following re-installation, has been operated at any time on a CFM56-5C engine.
- Subgroup 1C are CFM56-5C engines.

Group 2 engines are those that do not have an affected part installed.

**Re-installation:** For an affected part, first in-service re-installation on an HPT disc other than the HPT disc on which that affected part was originally installed in production.

### Reason:

Occurrences have been reported of finding cracked rotating air HPT front seals during in-shop inspections. Subsequent investigation determined that certain rotating air HPT front seals, if removed from an HPT disc and re-installed on a different HPT disc, may be susceptible to similar cracks.

This condition, if not detected and corrected, could lead to uncontained engine failure, possibly resulting in damage to the aeroplane, with consequent reduced control of the aeroplane.

To address this potential unsafe condition, CFM International issued the applicable S/B, providing instructions to replace the affected parts. Consequently, EASA issued AD 2019-0146 to require removal from service of the affected parts and to prohibit re-installation thereof.

After that AD was issued, prompted by operator comments, EASA issued AD 2019-0150, retaining the requirements of EASA AD 2019-0146, which was superseded, including clarifications, reference



to the applicable Engine Shop Manual for the existing life limits (not to be exceeded) and providing a full list of the affected serial numbers (Appendices 1 and 2).

Prompted by further operator comments, this AD retains the requirements of EASA AD 2019-0150, which is superseded, and introduces reduced life limits for affected parts which have been previously installed on different engine models. This AD also excludes from the definition of “affected part” certain parts, for which an installation requirement is added.

#### Required Action(s) and Compliance Time(s):

Required as indicated, unless accomplished previously:

#### Part Replacement:

- (1) For Group 1 engines: Within the compliance time as defined in Table 1 of this AD, as applicable, but without exceeding the applicable life limit as specified in Chapter 05 of the applicable Engine Shop Manual, replace the affected part with a serviceable part, as defined in this AD, in accordance with the instructions of the applicable S/B.

Table 1 – Affected Parts Replacement

Engine(s) (all models)	Compliance time (A, B, C or D, whichever occurs later, as applicable)
Subgroup 1A	<b>A:</b> Within 6 500 engine cycles (EC) since re-installation
	<b>B:</b> Within 500 EC after 05 July 2019 [the effective date of EASA AD 2019-0150], but not exceeding 7 000 EC since re-installation
	<b>C:</b> Within 50 EC after 05 July 2019 [the effective date of EASA AD 2019-0150]
Subgroup 1B	<b>A:</b> Within 4 000 EC since re-installation
	<b>B:</b> Within 250 EC after 05 July 2019 [the effective date of EASA AD 2019-0150], but not exceeding 4 250 EC since re-installation
	<b>C:</b> Within 1 500 EC since last seal piece-part fluorescent penetrant inspection
	<b>D:</b> Within 25 EC after the effective date of this AD, but not exceeding the compliance time applicable for Subgroup 1A engines
Subgroup 1C	<b>A:</b> Within 4 000 EC since re-installation
	<b>B:</b> Within 250 EC after 05 July 2019 [the effective date of EASA AD 2019-0150], but not exceeding 4 250 EC since re-installation
	<b>C:</b> Within 1 500 EC since last seal piece-part fluorescent penetrant inspection
	<b>D:</b> Within 25 EC after 05 July 2019 [the effective date of EASA AD 2019-0150]

#### Limitations:

- (2) From the effective date of this AD, do not operate an aeroplane having two Subgroup 1A engines installed, or two Subgroup 1B engines, or a combination thereof, equipped with an



affected part having accumulated 6 500 EC (Subgroup 1A) or more, or 4 000 EC (Subgroup 1B) or more since re-installation.

- (3) From the effective date of this AD, do not operate an aeroplane having two or more Subgroup 1C engines installed, equipped with an affected part having accumulated 4 000 EC or more since re-installation.

**Part(s) Installation:**

- (4) For Group 1 and Group 2 engines: From 05 July 2019 [the effective date of EASA AD 2019-0150], do not install (see Note 1 of this AD) an affected part on any engine.

Note 1: The following actions, accomplished during a single maintenance visit, are not considered as 'installation' as specified in paragraph (4) of this AD: Removing an affected part from its HPT disc and re-installing that affected part on the same disc on the same engine; removing an HPT disc equipped with an affected part and re-installing that disc, with that affected part, on the same engine.

- (5) For Group 1 and Group 2 engines: From the effective date of this AD, do not re-install a serviceable part, having P/N 1795M36P01 or P/N 1795M36P02, and having a s/n as identified in Appendix 1 (P/N 1795M36P01) or Appendix 2 (P/N 1795M36P02) of this AD, on any HPT disk different from the HPT disk on which that serviceable part was previously installed.

**Ref. Publications:**

CFM International S.A. CFM56-5B S/B 72-1074 original issue dated 27 July 2018, or Revision 01 dated 05 December 2018, or Revision 02 dated 06 November 2019.

CFM International S.A. CFM56-5C S/B 72-0794 original issue dated 14 September 2018, or Revision 01 dated 02 January 2019, or Revision 02 dated 06 November 2019.

CFM International S.A. CFM56-7B S/B 72-1042 original issue dated 27 July 2018, or Revision 01 dated 02 January 2019, or Revision 02 dated 06 November 2019.

The use of later approved revisions of the above-mentioned documents is acceptable for compliance with the requirements of this AD.

**Remarks:**

1. If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD
2. This AD was posted on 12 December 2019 as PAD 19-212 for consultation until 26 December 2019. No comments were received during the consultation period.
3. Enquiries regarding this AD should be referred to the EASA Programming and Continued Airworthiness Information Section, Certification Directorate. E-mail: [ADs@easa.europa.eu](mailto:ADs@easa.europa.eu).
4. Information about any failures, malfunctions, defects or other occurrences, which may be similar to the unsafe condition addressed by this AD, and which may occur, or have occurred on



a product, part or appliance not affected by this AD, can be reported to the [EU aviation safety reporting system](#).

5. For any question concerning the technical content of the requirements in this AD, please contact: CFM International S.A., Customer Support Centre, Telephone: +33 1 64 14 88 66, Fax: +33 1 64 79 85 55, E-mail: [cfm.csc@safrangroup.com](mailto:cfm.csc@safrangroup.com);  
or

CFM Inc. Aviation Operations Centre, Telephone: +1 513-552-3272, or +1 877-432-3272,  
Fax: +1 877-432-3329, E-mail: [geae.aoc@ge.com](mailto:geae.aoc@ge.com), or [aviation.fleetsupport@ge.com](mailto:aviation.fleetsupport@ge.com).



## Appendix 1 – P/N 1795M36P01 – Affected Serial Numbers

GWNDN949	GWNDS079	GWNKC901	GWNKE207	GWNKF192	GWNKG219
GWNDP018	GWNDS080	GWNKC902	GWNKE320	GWNKF193	GWNKG220
GWNDP019	GWNDS081	GWNKC903	GWNKE321	GWNKF194	GWNKG397
GWNDP020	GWNDS380	GWNKD506	GWNKE322	GWNKF288	GWNKG398
GWNDP021	GWNDS381	GWNKD507	GWNKE598	GWNKF289	GWNKG399
GWNDP901	GWNDS382	GWNKD508	GWNKE599	GWNKF314	GWNKG400
GWNDP902	GWNDS383	GWNKD723	GWNKE600	GWNKF315	GWNKG686
GWNDP903	GWNDS384	GWNKD724	GWNKE601	GWNKF316	GWNKG687
GWNDP904	GWNDS385	GWNKD725	GWNKE602	GWNKF317	GWNKG688
GWNDP905	GWNDS387	GWNKD726	GWNKE603	GWNKF676	GWNKG689
GWNDP906	GWNDS388	GWNKD727	GWNKE604	GWNKF677	GWNKG814
GWNDP907	GWNDS592	GWNKD732	GWNKE840	GWNKF678	GWNKG816
GWNDR152	GWNDS653	GWNKD796	GWNKE841	GWNKF679	GWNKG817
GWNDR402	GWNDS654	GWNKD797	GWNKE842	GWNKF680	GWNKH129
GWNDR403	GWNDS874	GWNKD798	GWNKE893	GWNKF681	GWNKH130
GWNDR404	GWNDS875	GWNKD824	GWNKE894	GWNKF682	GWNKH131
GWNDR405	GWNDS876	GWNKD825	GWNKE895	GWNKF683	GWNKH132
GWNDR406	GWNDS877	GWNKD826	GWNKE897	GWNKF684	GWNKH133
GWNDR529	GWNDS935	GWNKD827	GWNKF015	GWNKG073	GWNKH395
GWNDR530	GWNDS937	GWNKD828	GWNKF016	GWNKG074	GWNKH397
GWNDR531	GWNDS938	GWNKE045	GWNKF017	GWNKG075	GWNKH525
GWNDR532	GWNDT152	GWNKE046	GWNKF107	GWNKG076	GWNKH526
GWNDR955	GWNKC168	GWNKE047	GWNKF108	GWNKG077	GWNKH527
GWNDR956	GWNKC170	GWNKE048	GWNKF109	GWNKG078	GWNKH528
GWNDR957	GWNKC173	GWNKE049	GWNKF110	GWNKG080	GWNKH529
GWNDR958	GWNKC174	GWNKE050	GWNKF111	GWNKG081	GWNKH530
GWNDR960	GWNKC175	GWNKE205	GWNKF112	GWNKG217	GWNKH531
GWNDS078	GWNKC900	GWNKE206	GWNKF113	GWNKG218	



## Appendix 2 – P/N 1795M36P02 – Affected Serial Numbers

GWN000CE	GWN0028J	GWN0037L	GWN006MC	GWN006P2	GWN009P7
GWN000CF	GWN0028K	GWN0037M	GWN006MD	GWN006P3	GWN009P8
GWN000CG	GWN0028L	GWN0041F	GWN006ME	GWN006P4	GWN009P9
GWN000CH	GWN0028M	GWN0041G	GWN006MF	GWN006P5	GWN009PA
GWN000CJ	GWN0028N	GWN0041H	GWN006MG	GWN0073G	GWN009PC
GWN000CK	GWN0028R	GWN0041J	GWN006MH	GWN00757	GWN009PD
GWN000CL	GWN0028T	GWN0041K	GWN006MJ	GWN008EC	GWN009PE
GWN000CM	GWN0028V	GWN0041L	GWN006MK	GWN008ED	GWN009PF
GWN000CN	GWN0028W	GWN0041M	GWN006ML	GWN008EE	GWN009PG
GWN000CP	GWN0028Y	GWN0041N	GWN006MM	GWN008EF	GWN009PH
GWN000CR	GWN00290	GWN0041P	GWN006MN	GWN008EG	GWN009PJ
GWN000CT	GWN002WD	GWN0041R	GWN006MP	GWN008EH	GWN009PK
GWN000CV	GWN002WE	GWN0041T	GWN006MR	GWN008EJ	GWN009PL
GWN000CW	GWN002WG	GWN0041V	GWN006MT	GWN008EK	GWN009PM
GWN000CY	GWN002WH	GWN0041W	GWN006MV	GWN008EL	GWN009PN
GWN000D0	GWN002WJ	GWN0041Y	GWN006MW	GWN008EM	GWN00AV5
GWN000D2	GWN002WK	GWN00420	GWN006MY	GWN008EN	GWN00AV6
GWN000D3	GWN002WL	GWN00421	GWN006N0	GWN008EP	GWN00AV7
GWN000D4	GWN002WM	GWN00422	GWN006N1	GWN008ER	GWN00AV8
GWN001G3	GWN002WN	GWN00423	GWN006N2	GWN008ET	GWN00AV9
GWN001G4	GWN002WP	GWN00424	GWN006N3	GWN008EV	GWN00AVA
GWN001G5	GWN002WR	GWN00425	GWN006N4	GWN008EW	GWN00AVC
GWN001G6	GWN002WT	GWN004WM	GWN006N6	GWN008EY	GWN00AVD
GWN001G7	GWN002WV	GWN004WN	GWN006N7	GWN008F0	GWN00AVE
GWN001G8	GWN002WW	GWN004WP	GWN006N8	GWN00920	GWN00AVF
GWN001G9	GWN002WY	GWN004WR	GWN006N9	GWN00921	GWN00AVG
GWN001GA	GWN002Y0	GWN004WT	GWN006NA	GWN00922	GWN00CTK
GWN001GC	GWN002Y1	GWN0052H	GWN006NC	GWN00923	GWN00CTL
GWN001GD	GWN002Y2	GWN0052J	GWN006ND	GWN00924	GWN00CTM
GWN001GE	GWN0036Y	GWN0052K	GWN006NE	GWN00925	GWN00CTN
GWN001GF	GWN00371	GWN0052L	GWN006NF	GWN00926	GWN00CTP
GWN001GG	GWN00372	GWN0052M	GWN006NG	GWN00927	GWN00CTR
GWN001GH	GWN00373	GWN0052N	GWN006NH	GWN00928	GWN00CTT
GWN001GJ	GWN00374	GWN0052P	GWN006NJ	GWN00929	GWN00CTV
GWN001GK	GWN00376	GWN0052R	GWN006NK	GWN0092A	GWN00CTW
GWN001GL	GWN00377	GWN0052T	GWN006NL	GWN0092C	GWN00CTY
GWN001GM	GWN00378	GWN0052V	GWN006NM	GWN0092D	GWN00CV0
GWN001GN	GWN00379	GWN0052Y	GWN006NN	GWN0092E	GWN00CV1
GWN001GP	GWN0037A	GWN00530	GWN006NP	GWN0092F	GWN00CV2
GWN00289	GWN0037C	GWN00531	GWN006NR	GWN0092G	GWN00CV3
GWN0028A	GWN0037D	GWN00532	GWN006NT	GWN0092H	GWN00CV4
GWN0028C	GWN0037E	GWN00533	GWN006NV	GWN0092J	GWN00CV5
GWN0028D	GWN0037F	GWN00534	GWN006NW	GWN009NW	GWN00CV6
GWN0028E	GWN0037G	GWN00535	GWN006NY	GWN009P4	GWN00DGM
GWN0028G	GWN0037H	GWN006M9	GWN006P0	GWN009P5	GWN00DGN
GWN0028H	GWN0037K	GWN006MA	GWN006P1	GWN009P6	GWN00DGP



## Appendix 2 – P/N 1795M36P02 – Affected Serial Numbers

GWN00DGR	GWN00FDG	GWN00HDD	GWN00LDG	GWN00MH3	GWN00P4V
GWN00DGT	GWN00FDH	GWN00HDE	GWN00LDH	GWN00MH4	GWN00P4W
GWN00E20	GWN00G1R	GWN00HDF	GWN00LDJ	GWN00MH5	GWN00P4Y
GWN00E22	GWN00G1T	GWN00HDG	GWN00LDK	GWN00MH7	GWN00P50
GWN00E23	GWN00G1V	GWN00HDH	GWN00LDL	GWN00MH8	GWN00P51
GWN00E25	GWN00G1W	GWN00HDJ	GWN00LDM	GWN00MH9	GWN00P52
GWN00E26	GWN00G1Y	GWN00HDK	GWN00LDN	GWN00MHA	GWN00P53
GWN00E28	GWN00G20	GWN00HDL	GWN00LDP	GWN00MHC	GWN00P54
GWN00E29	GWN00G21	GWN00HDM	GWN00LDR	GWN00N9C	GWN00P55
GWN00E2A	GWN00G22	GWN00HDN	GWN00LDT	GWN00N9D	GWN00P56
GWN00E2C	GWN00G23	GWN00HDP	GWN00LDV	GWN00N9E	GWN00P57
GWN00E2D	GWN00G24	GWN00HDR	GWN00LDW	GWN00N9F	GWN00P58
GWN00E2E	GWN00G25	GWN00HDT	GWN00LDY	GWN00N9G	GWN00P59
GWN00E2F	GWN00G26	GWN00HDV	GWN00LE0	GWN00N9H	GWN00P5A
GWN00E2G	GWN00G27	GWN00HDW	GWN00LE1	GWN00N9J	GWN00P5C
GWN00E2H	GWN00G28	GWN00HDY	GWN00LE2	GWN00N9K	GWN00P5D
GWN00E2J	GWN00G29	GWN00HE0	GWN00LE3	GWN00N9L	GWN00P5E
GWN00ENL	GWN00G2A	GWN00HE1	GWN00LE4	GWN00N9M	GWN00P5F
GWN00ENM	GWN00G2C	GWN00HE2	GWN00LE5	GWN00N9N	GWN00P5G
GWN00ENN	GWN00GNJ	GWN00HE3	GWN00LE6	GWN00N9P	GWN00P5H
GWN00ENP	GWN00GNK	GWN00HE4	GWN00LE7	GWN00N9R	GWN00P5J
GWN00ENR	GWN00GNL	GWN00HE5	GWN00LE8	GWN00N9T	GWN00P5K
GWN00ENT	GWN00GNM	GWN00HE6	GWN00LE9	GWN00N9V	GWN00P5L
GWN00ENV	GWN00GNN	GWN00HE7	GWN00LR0	GWN00P23	GWN00P5M
GWN00ENW	GWN00GNP	GWN00HE8	GWN00LR1	GWN00P24	GWN00P5N
GWN00ENY	GWN00GNR	GWN00JNK	GWN00LR2	GWN00P25	GWN00PFV
GWN00EP0	GWN00GNT	GWN00JNL	GWN00LR3	GWN00P26	GWN00PP2
GWN00EP1	GWN00GNV	GWN00JNM	GWN00LR4	GWN00P45	GWN00PP3
GWN00EP2	GWN00GNW	GWN00JNN	GWN00LR5	GWN00P46	GWN00PP4
GWN00EP3	GWN00GNY	GWN00JNP	GWN00LR6	GWN00P47	GWN00PP5
GWN00EP4	GWN00GP0	GWN00JNR	GWN00LR7	GWN00P48	GWN00PP6
GWN00EP5	GWN00GP1	GWN00JNT	GWN00LR8	GWN00P49	GWN00PP7
GWN00FD1	GWN00GP2	GWN00JNV	GWN00LR9	GWN00P4A	GWN00PP8
GWN00FD2	GWN00GP3	GWN00JNW	GWN00LRA	GWN00P4C	GWN00PP9
GWN00FD3	GWN00GP4	GWN00JNY	GWN00LRC	GWN00P4D	GWN00PPA
GWN00FD4	GWN00HD1	GWN00JP0	GWN00LRD	GWN00P4E	GWN00PPC
GWN00FD5	GWN00HD2	GWN00JP1	GWN00LRE	GWN00P4G	GWN00PPD
GWN00FD6	GWN00HD3	GWN00JP2	GWN00LRF	GWN00P4H	GWN00PPE
GWN00FD7	GWN00HD4	GWN00JP3	GWN00LRG	GWN00P4J	GWN00PPF
GWN00FD8	GWN00HD5	GWN00LD8	GWN00MGT	GWN00P4K	GWN00PPG
GWN00FD9	GWN00HD6	GWN00LD9	GWN00MGV	GWN00P4L	GWN00PPH
GWN00FDA	GWN00HD7	GWN00LDA	GWN00MGW	GWN00P4M	GWN00PPJ
GWN00FDC	GWN00HD8	GWN00LDC	GWN00MGY	GWN00P4N	GWN00PPK
GWN00FDD	GWN00HD9	GWN00LDD	GWN00MH0	GWN00P4P	GWN00PPL
GWN00FDE	GWN00HDA	GWN00LDE	GWN00MH1	GWN00P4R	GWN00PPM
GWN00FDF	GWN00HDC	GWN00LDF	GWN00MH2	GWN00P4T	GWN00RA7





## Appendix 2 – P/N 1795M36P02 – Affected Serial Numbers

GWN00RA8	GWN00VL4	GWN00YEV	GWN010MR	GWN01270	GWN01480
GWN00RA9	GWN00VL5	GWN00YEW	GWN01181	GWN01271	GWN01481
GWN00RAA	GWN00VL6	GWN00YFY	GWN01182	GWN01272	GWN0148M
GWN00RAC	GWN00VL7	GWN00YF0	GWN01183	GWN01273	GWN0148N
GWN00RAD	GWN00VL8	GWN00YF1	GWN01184	GWN012NT	GWN0148P
GWN00RAE	GWN00VL9	GWN00YF2	GWN01185	GWN012NV	GWN014LG
GWN00RAF	GWN00VLA	GWN00YF3	GWN01186	GWN012NW	GWN014LH
GWN00RAG	GWN00VLC	GWN00YF4	GWN01187	GWN012NY	GWN014LJ
GWN00RAH	GWN00YDF	GWN00YF5	GWN01188	GWN012P0	GWN014LK
GWN00RAK	GWN00YDG	GWN00YF7	GWN01189	GWN012P1	GWN014LL
GWN00RAL	GWN00YDH	GWN00YF8	GWN0118A	GWN012P2	GWN014LM
GWN00TFH	GWN00YDJ	GWN00YF9	GWN0118C	GWN012P3	GWN014LN
GWN00TFJ	GWN00YDK	GWN00YFA	GWN0118D	GWN012P4	GWN014LP
GWN00TFK	GWN00YDL	GWN00YFC	GWN0118E	GWN012P5	GWN014LR
GWN00TFL	GWN00YDM	GWN00YFD	GWN011E3	GWN012P6	GWN014LW
GWN00TFM	GWN00YDN	GWN00YFE	GWN011EN	GWN012P7	GWN014LY
GWN00TFN	GWN00YDP	GWN00YFF	GWN011EP	GWN013LM	GWN014M0
GWN00TFP	GWN00YDR	GWN00YFG	GWN011ER	GWN013LN	GWN014N5
GWN00TFR	GWN00YDT	GWN00YFH	GWN011EV	GWN013LP	GWN014N6
GWN00TFT	GWN00YDV	GWN00YFJ	GWN011F2	GWN013LR	GWN014N7
GWN00TFV	GWN00YDW	GWN00YFK	GWN011F3	GWN013LT	GWN0154K
GWN00TFW	GWN00YDY	GWN00YFL	GWN011F4	GWN013LV	GWN0154L
GWN00TFY	GWN00YE0	GWN00YFM	GWN011F5	GWN013LW	GWN01591
GWN00TG0	GWN00YE1	GWN00YFN	GWN011F6	GWN013LY	GWN01592
GWN00TG1	GWN00YE2	GWN00YFP	GWN011F7	GWN013M0	GWN01593
GWN00TG2	GWN00YE3	GWN0108P	GWN01206	GWN013M1	GWN01594
GWN00TG3	GWN00YE4	GWN0108R	GWN01207	GWN013M2	GWN01595
GWN00TG4	GWN00YE5	GWN0108T	GWN01208	GWN013M3	GWN01596
GWN00TG5	GWN00YE6	GWN0108V	GWN01209	GWN013M4	GWN01597
GWN00TG6	GWN00YE7	GWN0108Y	GWN0120A	GWN013M5	GWN01598
GWN00TG7	GWN00YE8	GWN01090	GWN0120C	GWN013M6	GWN01599
GWN00TG8	GWN00YE9	GWN01091	GWN0120D	GWN013M7	GWN0159A
GWN00TG9	GWN00YEA	GWN01092	GWN0120E	GWN013M8	GWN0159C
GWN00TGA	GWN00YEC	GWN01093	GWN0120F	GWN013M9	GWN0159D
GWN00V3M	GWN00YED	GWN01094	GWN0120G	GWN013MA	GWN0159E
GWN00V3N	GWN00YEE	GWN01095	GWN0120H	GWN013MC	GWN0159F
GWN00VKP	GWN00YEF	GWN01096	GWN0120J	GWN013MD	GWN0159G
GWN00VKR	GWN00YEG	GWN01097	GWN0120K	GWN013ME	GWN0159H
GWN00VKT	GWN00YEH	GWN01098	GWN0120L	GWN013MF	GWN0159J
GWN00VKV	GWN00YEJ	GWN01099	GWN0120M	GWN013MG	GWN0159K
GWN00VKW	GWN00YEK	GWN010MJ	GWN0126P	GWN0147P	GWN0159L
GWN00VKY	GWN00YEM	GWN010MK	GWN0126R	GWN0147R	GWN0159M
GWN00VL0	GWN00YEN	GWN010ML	GWN0126T	GWN0147T	GWN0159N
GWN00VL1	GWN00YEP	GWN010MM	GWN0126V	GWN0147V	GWN0159P
GWN00VL2	GWN00YER	GWN010MN	GWN0126W	GWN0147W	GWN0159R
GWN00VL3	GWN00YET	GWN010MP	GWN0126Y	GWN0147Y	GWN0159T



## Appendix 2 – P/N 1795M36P02 – Affected Serial Numbers

GWN01647	GWN019CF	GWN019H0	GWN01C3Y	GWN01CKC	GWN01F22
GWN01648	GWN019CG	GWN019H1	GWN01C40	GWN01CKD	GWN01F23
GWN016V4	GWN019CH	GWN019H2	GWN01C41	GWN01CKE	GWN01F24
GWN016V5	GWN019CJ	GWN019H3	GWN01C42	GWN01CKF	GWN01F25
GWN016V6	GWN019CK	GWN019H4	GWN01C43	GWN01CKG	GWN01F26
GWN016V7	GWN019CL	GWN019H5	GWN01C44	GWN01CKH	GWN01F27
GWN016V8	GWN019CM	GWN019H6	GWN01C45	GWN01CKJ	GWN01F28
GWN016V9	GWN019CN	GWN019H7	GWN01C46	GWN01CKK	GWN01F29
GWN016VA	GWN019CP	GWN019H8	GWN01C47	GWN01CKL	GWN01F2A
GWN016VC	GWN019CR	GWN019H9	GWN01C48	GWN01CKM	GWN01F2C
GWN016VD	GWN019CT	GWN019HA	GWN01C49	GWN01CKN	GWN01F2D
GWN0178D	GWN019CV	GWN019HC	GWN01C4A	GWN01CKP	GWN01F2E
GWN0178E	GWN019CW	GWN019HD	GWN01C4C	GWN01DJY	GWN01F2F
GWN0178F	GWN019CY	GWN019HE	GWN01C4D	GWN01DK0	GWN01FNT
GWN0178G	GWN019D0	GWN019HF	GWN01C4E	GWN01DK1	GWN01FNV
GWN017PR	GWN019D1	GWN019HG	GWN01C4F	GWN01DK2	GWN01FNW
GWN017PT	GWN019D2	GWN019HH	GWN01C4G	GWN01DK3	GWN01FNY
GWN017PW	GWN019D3	GWN019PW	GWN01C4H	GWN01DK4	GWN01FP0
GWN017PY	GWN019D4	GWN019PY	GWN01C4J	GWN01DK5	GWN01FP1
GWN017R0	GWN019D5	GWN019R0	GWN01C4K	GWN01DK6	GWN01FP2
GWN017R1	GWN019D6	GWN019R1	GWN01C4L	GWN01DK7	GWN01FP3
GWN017R2	GWN019D7	GWN019R2	GWN01C4M	GWN01DK8	GWN01FP4
GWN017R3	GWN019D8	GWN019R3	GWN01C4N	GWN01DK9	GWN01FP5
GWN018W7	GWN019G5	GWN019R4	GWN01C4P	GWN01DKA	GWN01FP6
GWN018W8	GWN019G6	GWN019R5	GWN01C4R	GWN01DKC	GWN01FP7
GWN018W9	GWN019G7	GWN019R6	GWN01C4T	GWN01DKD	GWN01FP8
GWN018WA	GWN019G8	GWN019R7	GWN01C4V	GWN01DKE	GWN01FP9
GWN018WC	GWN019G9	GWN019R8	GWN01C4W	GWN01DKF	GWN01FPA
GWN01961	GWN019GA	GWN019R9	GWN01C4Y	GWN01EET	GWN01FPC
GWN01962	GWN019GC	GWN019RA	GWN01C50	GWN01EEV	GWN01FPD
GWN01963	GWN019GD	GWN019RC	GWN01C51	GWN01EEW	GWN01GKD
GWN01964	GWN019GE	GWN01C3D	GWN01C52	GWN01EEY	GWN01GKE
GWN01965	GWN019GF	GWN01C3E	GWN01C53	GWN01EF0	GWN01GKF
GWN01966	GWN019GG	GWN01C3F	GWN01C54	GWN01EF1	GWN01GKG
GWN01967	GWN019GH	GWN01C3G	GWN01C55	GWN01EF2	GWN01GKH
GWN01968	GWN019GJ	GWN01C3H	GWN01C56	GWN01EF3	GWN01GKJ
GWN01969	GWN019GK	GWN01C3J	GWN01C57	GWN01EF5	GWN01GKK
GWN019C4	GWN019GL	GWN01C3K	GWN01C58	GWN01EF6	GWN01GKL
GWN019C5	GWN019GM	GWN01C3L	GWN01C59	GWN01EF7	GWN01GKM
GWN019C6	GWN019GN	GWN01C3M	GWN01CK4	GWN01EF8	GWN01GKN
GWN019C7	GWN019GP	GWN01C3N	GWN01CK5	GWN01EF9	GWN01GKP
GWN019C8	GWN019GR	GWN01C3P	GWN01CK6	GWN01EFA	GWN01GKR
GWN019C9	GWN019GT	GWN01C3R	GWN01CK7	GWN01EFC	GWN01GKT
GWN019CA	GWN019GV	GWN01C3T	GWN01CK8	GWN01F1W	GWN01GKV
GWN019CC	GWN019GW	GWN01C3V	GWN01CK9	GWN01F1Y	GWN01GKW
GWN019CE	GWN019GY	GWN01C3W	GWN01CKA	GWN01F21	GWN01GKY



## Appendix 2 – P/N 1795M36P02 – Affected Serial Numbers

GWN01GL0	GWN022D7	GWN025K0	GWN028FT	GWN02A9M	GWN02CR0
GWN01GL1	GWN022D8	GWN025K1	GWN028FW	GWN02A9N	GWN02CR1
GWN01W3T	GWN022D9	GWN025K2	GWN028G0	GWN02A9P	GWN02CR2
GWN01W3W	GWN022E5	GWN025K3	GWN028G1	GWN02A9R	GWN02CR3
GWN01W40	GWN022EP	GWN025K4	GWN028J7	GWN02A9T	GWN02CR4
GWN01W41	GWN0239K	GWN025K5	GWN028J8	GWN02A9W	GWN02CR5
GWN01W42	GWN0239L	GWN025K6	GWN028J9	GWN02AA1	GWN02CR6
GWN02044	GWN0239M	GWN025K7	GWN028JA	GWN02AA5	GWN02CR7
GWN02045	GWN0239N	GWN025K8	GWN028JC	GWN02AA8	GWN02CR8
GWN02046	GWN0239P	GWN025K9	GWN028JD	GWN02AAC	GWN02CR9
GWN02047	GWN0239R	GWN025KA	GWN028JE	GWN02AAF	GWN02CRA
GWN02048	GWN0239T	GWN025KC	GWN028JF	GWN02AAM	GWN02DHD
GWN02049	GWN0239W	GWN025KD	GWN028JG	GWN02AAR	GWN02DHE
GWN0204D	GWN023A0	GWN0270T	GWN028JH	GWN02AAT	GWN02DHF
GWN0204F	GWN023A1	GWN0270W	GWN028JJ	GWN02AAW	GWN02DHG
GWN0204G	GWN023A2	GWN02710	GWN028JK	GWN02AC2	GWN02DHH
GWN0204H	GWN023A3	GWN02711	GWN028JL	GWN02AC3	GWN02DHJ
GWN0204K	GWN023A4	GWN02712	GWN028JM	GWN02ACT	GWN02DHK
GWN0204L	GWN023A5	GWN02713	GWN028JP	GWN02APD	GWN02DHL
GWN0204M	GWN0243G	GWN02714	GWN028JR	GWN02APE	GWN02DHM
GWN0204N	GWN0243H	GWN02715	GWN028JT	GWN02APF	GWN02DHN
GWN0204P	GWN0243J	GWN02716	GWN028JW	GWN02APG	GWN02DHP
GWN020T8	GWN0243K	GWN02717	GWN028K0	GWN02APH	GWN02DHR
GWN020T9	GWN0243L	GWN02718	GWN028K2	GWN02APJ	GWN02DHW
GWN020TA	GWN0243M	GWN02719	GWN028TR	GWN02APK	GWN02DLG
GWN020TC	GWN0243N	GWN0271A	GWN028TT	GWN02APL	GWN02DLJ
GWN020TD	GWN0243P	GWN0271C	GWN028TW	GWN02APM	GWN02FL7
GWN020TE	GWN0243R	GWN0271E	GWN028W0	GWN02C8G	GWN02FL8
GWN020TF	GWN0243T	GWN0271F	GWN028W1	GWN02C8H	GWN02FL9
GWN020TG	GWN0243W	GWN0271G	GWN028W2	GWN02C8J	GWN02FLA
GWN020TH	GWN02440	GWN0271H	GWN028W3	GWN02C8K	GWN02FLC
GWN020TJ	GWN02441	GWN0271J	GWN028W4	GWN02C8L	GWN02FLD
GWN020TK	GWN0246J	GWN02779	GWN028W5	GWN02C8M	GWN02FLE
GWN020TL	GWN0246K	GWN0277A	GWN028W6	GWN02C8N	GWN02FLF
GWN022CM	GWN0246L	GWN0277C	GWN028W7	GWN02C8P	GWN02FLG
GWN022CN	GWN0246N	GWN0277D	GWN0297E	GWN02C8R	GWN02FLH
GWN022CP	GWN0246P	GWN02890	GWN0297F	GWN02C8T	GWN02FLJ
GWN022CR	GWN0246R	GWN028FG	GWN0297G	GWN02C8W	GWN02FLK
GWN022CW	GWN0246T	GWN028FH	GWN0297H	GWN02CPJ	GWN02FLL
GWN022D0	GWN0246W	GWN028FJ	GWN0297J	GWN02CPL	GWN02FLM
GWN022D1	GWN02470	GWN028FK	GWN0297K	GWN02CPM	GWN02FLP
GWN022D2	GWN02471	GWN028FL	GWN0297L	GWN02CPN	GWN02FLR
GWN022D3	GWN02472	GWN028FM	GWN0297N	GWN02CPP	GWN02FLT
GWN022D4	GWN02473	GWN028FN	GWN0297P	GWN02CPR	GWN02FLW
GWN022D5	GWN025CC	GWN028FP	GWN02A9K	GWN02CPT	GWN02FM0
GWN022D6	GWN025CD	GWN028FR	GWN02A9L	GWN02CPW	GWN02FM1



## Appendix 2 – P/N 1795M36P02 – Affected Serial Numbers

GWN02FM2	GWN02HL1	GWN02L18	GWN02MCJ	GWN02PEC	GWN02W6A
GWN02FM3	GWN02HL2	GWN02L1A	GWN02MCK	GWN02PED	GWN02W6C
GWN02FM4	GWN02HL3	GWN02L1C	GWN02MCL	GWN02PEE	GWN02W6D
GWN02FM5	GWN02HL4	GWN02L1D	GWN02MCM	GWN02PEF	GWN02W6E
GWN02FM6	GWN02HL5	GWN02L1G	GWN02MCN	GWN02RHP	GWN02W6F
GWN02FM7	GWN02HL6	GWN02L1H	GWN02MCP	GWN02RHR	GWN02W6G
GWN02FM8	GWN02HL7	GWN02L1J	GWN02MCR	GWN02RHT	GWN02W6H
GWN02GJ0	GWN02HL8	GWN02LJ7	GWN02MCT	GWN02RHW	GWN02W6J
GWN02GJ1	GWN02HL9	GWN02LJ8	GWN02NG6	GWN02RJ0	GWN02W6K
GWN02GJ2	GWN02J8N	GWN02LJ9	GWN02NG7	GWN02RJ1	GWN02W6L
GWN02GJ4	GWN02JC2	GWN02LJA	GWN02NG8	GWN02RJ2	GWN03001
GWN02GJ5	GWN02K0L	GWN02LJC	GWN02NG9	GWN02RJ3	GWN03002
GWN02GJ6	GWN02K0M	GWN02LJD	GWN02NGA	GWN02RJ4	GWN03003
GWN02GJ7	GWN02K0N	GWN02LJE	GWN02NGC	GWN02RJ5	GWN03004
GWN02GJ9	GWN02K0P	GWN02LJF	GWN02NGD	GWN02RJ6	GWN03005
GWN02GJA	GWN02K0R	GWN02LJG	GWN02NGE	GWN02RJ7	GWN03006
GWN02GJC	GWN02K0T	GWN02LJH	GWN02NGF	GWN02RJ8	GWN03007
GWN02GJD	GWN02K0W	GWN02LJJ	GWN02NGG	GWN02RJ9	GWN03008
GWN02GJE	GWN02K10	GWN02LJK	GWN02NGH	GWN02RJC	GWN03009
GWN02GJF	GWN02K11	GWN02LJL	GWN02NGJ	GWN02RJE	GWN0300A
GWN02GJG	GWN02K12	GWN02LJM	GWN02NGK	GWN02RJF	GWN0300C
GWN02GJJ	GWN02K13	GWN02LJN	GWN02NGL	GWN02RJH	GWN0300M
GWN02GJK	GWN02K14	GWN02LJP	GWN02NGM	GWN02RJJ	GWN0300LN
GWN02GJL	GWN02K15	GWN02LJR	GWN02NGN	GWN02RJL	GWN0300LP
GWN02GJM	GWN02K16	GWN02LJT	GWN02NGP	GWN02T5K	GWN0300LR
GWN02GJN	GWN02K17	GWN02LJW	GWN02NGR	GWN02T5L	GWN0300LT
GWN02GJP	GWN02K19	GWN02LK0	GWN02NGT	GWN02T5M	GWN0300LW
GWN02GJR	GWN02K1A	GWN02LK1	GWN02P7J	GWN02T5N	GWN0300M0
GWN02GJT	GWN02K1C	GWN02LK2	GWN02P7K	GWN02T5P	GWN0300M1
GWN02GJW	GWN02K1D	GWN02LK3	GWN02P7L	GWN02T5R	GWN0300M2
GWN02GK0	GWN02K1E	GWN02LK4	GWN02P7M	GWN02T5T	GWN031J2
GWN02GK1	GWN02K1F	GWN02MC1	GWN02PDN	GWN02T5W	GWN031J5
GWN02GK2	GWN02LOG	GWN02MC2	GWN02PDP	GWN02T60	GWN031J6
GWN02GK3	GWN02LOJ	GWN02MC3	GWN02PDR	GWN02T61	GWN031J7
GWN02GK4	GWN02LOK	GWN02MC4	GWN02PDT	GWN02T62	GWN031J8
GWN02GK5	GWN02LOL	GWN02MC5	GWN02PDW	GWN02T63	GWN031J9
GWN02GK6	GWN02LON	GWN02MC6	GWN02PE0	GWN02T64	GWN031JA
GWN02GK7	GWN02LOP	GWN02MC7	GWN02PE1	GWN02T65	GWN031JC
GWN02GK8	GWN02LOR	GWN02MC8	GWN02PE2	GWN02T66	GWN031JD
GWN02GK9	GWN02LOW	GWN02MC9	GWN02PE4	GWN02T67	GWN031JE
GWN02GKA	GWN02L10	GWN02MCA	GWN02PE5	GWN02T68	GWN031JF
GWN02GKC	GWN02L11	GWN02MCC	GWN02PE6	GWN02T69	GWN031JG
GWN02GKD	GWN02L13	GWN02MCD	GWN02PE7	GWN02T6A	GWN031JH
GWN02GKE	GWN02L14	GWN02MCE	GWN02PE8	GWN02T6C	GWN031JK
GWN02HKW	GWN02L16	GWN02MCG	GWN02PE9	GWN02W68	GWN031JL
GWN02HL0	GWN02L17	GWN02MCH	GWN02PEA	GWN02W69	GWN031JM



## Appendix 2 – P/N 1795M36P02 – Affected Serial Numbers

GWN031JN	GWN03462	GWN03679	GWN03896	GWN03A55	GWN03CPH
GWN031JP	GWN03463	GWN0367A	GWN03897	GWN03A56	GWN03CPJ
GWN031JR	GWN03464	GWN0367C	GWN03898	GWN03C1D	GWN03CPL
GWN0329A	GWN03465	GWN0367D	GWN03899	GWN03C1E	GWN03CPM
GWN0329C	GWN03466	GWN0367E	GWN038NE	GWN03C1F	GWN03CPP
GWN0329D	GWN03467	GWN0367F	GWN038NF	GWN03C1G	GWN03CPT
GWN0329E	GWN03468	GWN0367J	GWN038NG	GWN03C1H	GWN03CR1
GWN0329F	GWN03469	GWN0367K	GWN038NH	GWN03C1J	GWN03CR3
GWN0329G	GWN0346A	GWN0367L	GWN038NJ	GWN03C1K	GWN03CR4
GWN0329H	GWN0346C	GWN0367M	GWN038NK	GWN03C1L	GWN03CR5
GWN0329J	GWN0346D	GWN0367N	GWN038NL	GWN03C1M	GWN03CR6
GWN0329K	GWN0346E	GWN03737	GWN038NM	GWN03C1N	GWN03DT3
GWN0329L	GWN0346F	GWN03738	GWN038NN	GWN03C1P	GWN03DT4
GWN0329M	GWN0346G	GWN03739	GWN038NP	GWN03C1R	GWN03DT5
GWN0329N	GWN0346H	GWN0373A	GWN038NR	GWN03C1T	GWN03DT6
GWN0329P	GWN0346J	GWN0373C	GWN038NT	GWN03C1W	GWN03DT7
GWN0329R	GWN0346K	GWN0373D	GWN038NW	GWN03C20	GWN03DT8
GWN0329T	GWN0346L	GWN0373E	GWN038P0	GWN03C21	GWN03DT9
GWN0329W	GWN0346M	GWN0373F	GWN038P1	GWN03C22	GWN03DTA
GWN032A0	GWN03541	GWN0373G	GWN038P2	GWN03C24	GWN03DTC
GWN032A1	GWN03542	GWN0373H	GWN038P3	GWN03C25	GWN03EE7
GWN032A2	GWN03543	GWN0373J	GWN038P4	GWN03CMM	GWN03EEM
GWN032A3	GWN03544	GWN0373K	GWN038P9	GWN03CMW	GWN03EEN
GWN032A4	GWN03545	GWN0373L	GWN039R8	GWN03CN2	GWN03EEP
GWN0333A	GWN03546	GWN0373M	GWN039RC	GWN03CN5	GWN03EER
GWN0333C	GWN03547	GWN0373N	GWN039RE	GWN03CN6	GWN03EET
GWN0333D	GWN03548	GWN0373P	GWN039RF	GWN03CN7	GWN03EEW
GWN0333K	GWN03549	GWN0373R	GWN039RG	GWN03CN8	GWN03EF0
GWN0333N	GWN0354A	GWN0373T	GWN039RH	GWN03CN9	GWN03EF1
GWN03340	GWN0354C	GWN0373W	GWN039RJ	GWN03CNA	GWN03EF2
GWN03348	GWN0354D	GWN03740	GWN039RK	GWN03CNC	GWN03EF3
GWN0334C	GWN0354F	GWN0388J	GWN039RL	GWN03CND	GWN03EF4
GWN0334F	GWN0354H	GWN0388K	GWN039RM	GWN03CNE	GWN03EF5
GWN0334G	GWN0354J	GWN0388L	GWN039RN	GWN03CNF	GWN03EF6
GWN0334H	GWN0354K	GWN0388M	GWN039RP	GWN03CNH	GWN03EF8
GWN0334J	GWN0354L	GWN0388N	GWN039RR	GWN03CNJ	GWN03EF9
GWN0334K	GWN0354M	GWN0388P	GWN039RT	GWN03CNL	GWN03EFA
GWN0334M	GWN0354N	GWN0388R	GWN039RW	GWN03CNM	GWN03F3G
GWN0334N	GWN03671	GWN0388T	GWN039T0	GWN03CNN	GWN03F3H
GWN0334R	GWN03672	GWN0388W	GWN039T1	GWN03CNR	GWN03F3J
GWN03359	GWN03673	GWN03890	GWN039T2	GWN03CNT	GWN03F3K
GWN0335A	GWN03674	GWN03891	GWN03A50	GWN03CP0	GWN03F3L
GWN0335C	GWN03675	GWN03892	GWN03A51	GWN03CP1	GWN03F3M
GWN0345W	GWN03676	GWN03893	GWN03A52	GWN03CP2	GWN03F3N
GWN03460	GWN03677	GWN03894	GWN03A53	GWN03CP4	GWN03F3P
GWN03461	GWN03678	GWN03895	GWN03A54	GWN03CP5	GWN03F3R



## Appendix 2 – P/N 1795M36P02 – Affected Serial Numbers

GWN03F3T	GWN03HWH	GWN03KW4	GWN03N7A	GWN03R80	GWN03WFJ
GWN03F3W	GWN03HWJ	GWN03KW5	GWN03N7C	GWN03R81	GWN03WFK
GWN03F40	GWN03HWK	GWN03KW6	GWN03N7D	GWN03R82	GWN03WFL
GWN03F41	GWN03HWL	GWN03KW7	GWN03N7E	GWN03R84	GWN03WFM
GWN03F42	GWN03HWM	GWN03KW8	GWN03N7F	GWN03R85	GWN03WFN
GWN03F43	GWN03HWN	GWN03KW9	GWN03N7G	GWN03R86	GWN03WFP
GWN03F44	GWN03HWP	GWN03KWA	GWN03N7H	GWN03R87	GWN03WFR
GWN03F45	GWN03J02	GWN03KWC	GWN03N7J	GWN03R88	GWN03WFT
GWN03F46	GWN03J03	GWN03KWD	GWN03NJE	GWN03R89	GWN03WFW
GWN03G7H	GWN03J04	GWN03KWE	GWN03NJF	GWN03R8A	GWN03WG0
GWN03G7J	GWN03J05	GWN03KWF	GWN03NJG	GWN03R8C	GWN03WG1
GWN03G7K	GWN03J06	GWN03KWG	GWN03NJH	GWN03R8D	GWN03WG2
GWN03G7L	GWN03J07	GWN03KWH	GWN03NJJ	GWN03R8E	GWN03WG3
GWN03G7M	GWN03J08	GWN03KWK	GWN03NJK	GWN03R8F	GWN03WG4
GWN03G7N	GWN03J09	GWN03KWL	GWN03NJL	GWN03R8G	GWN03WG5
GWN03G7P	GWN03J0C	GWN03KWM	GWN03NJM	GWN03RJ6	GWN03WG6
GWN03G7R	GWN03J0D	GWN03KWN	GWN03NJN	GWN03RJ7	GWN03WG7
GWN03G7T	GWN03J0E	GWN03LW1	GWN03NJP	GWN03RJ8	GWN03WG8
GWN03G7W	GWN03J0F	GWN03LWG	GWN03NJR	GWN03RJ9	GWN03WG9
GWN03G80	GWN03J0G	GWN03LWH	GWN03NJT	GWN03RJA	GWN0410A
GWN03G81	GWN03J0H	GWN03LWJ	GWN03NJW	GWN03T8R	GWN0410C
GWN03G82	GWN03J0J	GWN03LWK	GWN03NK0	GWN03T8W	GWN0410D
GWN03G84	GWN03J9E	GWN03LWL	GWN03NK1	GWN03T90	GWN0410E
GWN03G85	GWN03J9F	GWN03LWM	GWN03R0C	GWN03T91	GWN0410F
GWN03G86	GWN03KHD	GWN03LWN	GWN03R0G	GWN03WE7	GWN0410G
GWN03G87	GWN03KHF	GWN03LWP	GWN03R0J	GWN03WE8	GWN0410H
GWN03G88	GWN03KHG	GWN03LWR	GWN03R0K	GWN03WE9	GWN0410J
GWN03G89	GWN03KHH	GWN03LWT	GWN03R0L	GWN03WEA	GWN0410K
GWN03G8A	GWN03KHJ	GWN03LWW	GWN03R0N	GWN03WEC	GWN0410L
GWN03H96	GWN03KHK	GWN03M00	GWN03R0P	GWN03WED	GWN0410M
GWN03H97	GWN03KHL	GWN03M01	GWN03R0W	GWN03WEE	GWN0410N
GWN03HLD	GWN03KHM	GWN03M02	GWN03R10	GWN03WEF	GWN0410P
GWN03HLE	GWN03KHN	GWN03M03	GWN03R12	GWN03WEG	GWN0410R
GWN03HLF	GWN03KHP	GWN03M04	GWN03R13	GWN03WEH	GWN0410T
GWN03HLG	GWN03KHR	GWN03M05	GWN03R14	GWN03WEK	GWN0410W
GWN03HLH	GWN03KHT	GWN03M06	GWN03R15	GWN03WF6	GWN04110
GWN03HLJ	GWN03KHW	GWN03M07	GWN03R16	GWN03WF7	GWN041KP
GWN03HLK	GWN03KJ0	GWN03MEG	GWN03R17	GWN03WF8	GWN041KR
GWN03HLL	GWN03KJ1	GWN03MEH	GWN03R7J	GWN03WF9	GWN041KT
GWN03HLM	GWN03KJ2	GWN03N72	GWN03R7K	GWN03WFA	GWN041KW
GWN03HLN	GWN03KJ3	GWN03N74	GWN03R7M	GWN03WFC	GWN041L0
GWN03HLP	GWN03KJ4	GWN03N75	GWN03R7N	GWN03WFD	GWN041L1
GWN03HLR	GWN03KJ5	GWN03N76	GWN03R7P	GWN03WFE	GWN041L2
GWN03HLT	GWN03KW1	GWN03N77	GWN03R7R	GWN03WFF	GWN041N7
GWN03HLW	GWN03KW2	GWN03N78	GWN03R7T	GWN03WFG	GWN041N8
GWN03HMO	GWN03KW3	GWN03N79	GWN03R7W	GWN03WFH	GWN041N9



## Appendix 2 – P/N 1795M36P02 – Affected Serial Numbers

GWN041NA	GWN04367	GWN0470C	GWN047L4	GWN04AM5	GWN04CKR
GWN041NC	GWN04368	GWN0470D	GWN047L5	GWN04AM6	GWN04CKT
GWN041ND	GWN04369	GWN0470E	GWN047L6	GWN04AM7	GWN04CKW
GWN041NE	GWN0436A	GWN0470F	GWN047L7	GWN04AM8	GWN04CLO
GWN041NF	GWN0436D	GWN0470G	GWN047L8	GWN04AM9	GWN04D5A
GWN041NG	GWN0436E	GWN0470H	GWN047L9	GWN04AMA	GWN04D5C
GWN041NH	GWN043F1	GWN047E2	GWN047LA	GWN04AMC	GWN04D5D
GWN041NJ	GWN043F2	GWN047E3	GWN047LC	GWN04AMD	GWN04D5E
GWN041NK	GWN043F3	GWN047E4	GWN047LD	GWN04AME	GWN04D5F
GWN041NL	GWN043F4	GWN047E5	GWN047LE	GWN04AMF	GWN04D5G
GWN041NM	GWN043F5	GWN047E6	GWN047LF	GWN04AMG	GWN04D5H
GWN041NN	GWN043F6	GWN047E7	GWN048D4	GWN04AMH	GWN04D5J
GWN041NP	GWN043F7	GWN047E8	GWN048D5	GWN04AMJ	GWN04D5K
GWN041NR	GWN043F9	GWN047E9	GWN048D6	GWN04AMK	GWN04D5L
GWN041NT	GWN043FA	GWN047EA	GWN048D7	GWN04AML	GWN04D5M
GWN041NW	GWN043FD	GWN047EC	GWN048D8	GWN04AMM	GWN04D5N
GWN041P0	GWN043FE	GWN047ED	GWN048D9	GWN04AMN	GWN04D5P
GWN041P1	GWN043FF	GWN047EE	GWN048DA	GWN04AMP	GWN04D5R
GWN041P2	GWN043FG	GWN047EF	GWN048DC	GWN04AMR	GWN04D5T
GWN042JT	GWN043FH	GWN047EG	GWN048DD	GWN04AMT	GWN04D5W
GWN042JW	GWN043GF	GWN047EH	GWN048DE	GWN04AMW	GWN04D60
GWN042K0	GWN04678	GWN047EJ	GWN04990	GWN04AN0	GWN04D61
GWN042K1	GWN04679	GWN047EK	GWN04A8D	GWN04AN1	GWN04D62
GWN042K2	GWN0467A	GWN047EL	GWN04A8E	GWN04AN2	GWN04D63
GWN042K3	GWN0467C	GWN047EM	GWN04A8F	GWN04AN3	GWN04D64
GWN042K4	GWN0467D	GWN047EN	GWN04A8G	GWN04AN6	GWN04D65
GWN042K5	GWN0467E	GWN047KA	GWN04A8H	GWN04AN7	GWN04D66
GWN042K6	GWN046D5	GWN047KC	GWN04A8K	GWN04AN8	GWN04D67
GWN042K7	GWN046D7	GWN047KD	GWN04A8L	GWN04ANA	GWN04D68
GWN042K8	GWN046D9	GWN047KE	GWN04AC3	GWN04CC5	GWN04D69
GWN042K9	GWN046DD	GWN047KF	GWN04AC4	GWN04CC6	GWN04D6A
GWN042KA	GWN046E1	GWN047KG	GWN04AC5	GWN04CC7	GWN04DCD
GWN042KC	GWN046E4	GWN047KH	GWN04AC6	GWN04CC8	GWN04DCE
GWN042KD	GWN046ET	GWN047KJ	GWN04AC7	GWN04CC9	GWN04DNC
GWN042KE	GWN046EW	GWN047KK	GWN04AC8	GWN04CCA	GWN04DND
GWN042KG	GWN046F0	GWN047KL	GWN04ACJ	GWN04CCC	GWN04DNE
GWN042KH	GWN046F1	GWN047KM	GWN04ACK	GWN04CJK	GWN04DNF
GWN042KJ	GWN046F2	GWN047KN	GWN04ACL	GWN04CK0	GWN04DNG
GWN042KK	GWN046F3	GWN047KP	GWN04ACM	GWN04CK4	GWN04DNH
GWN042KL	GWN04704	GWN047KR	GWN04ACN	GWN04CK7	GWN04DNJ
GWN042KM	GWN04705	GWN047KT	GWN04ACP	GWN04CKC	GWN04DNK
GWN042KN	GWN04706	GWN047KW	GWN04ACR	GWN04CKF	GWN04DNL
GWN042KP	GWN04707	GWN047L0	GWN04ACT	GWN04CKJ	GWN04DNM
GWN042KR	GWN04708	GWN047L1	GWN04ACW	GWN04CKM	GWN04DNN
GWN042KT	GWN04709	GWN047L2	GWN04AD0	GWN04CKN	GWN04DNP
GWN042KW	GWN0470A	GWN047L3	GWN04AD1	GWN04CKP	GWN04DNR



## Appendix 2 – P/N 1795M36P02 – Affected Serial Numbers

GWN04DNT	GWN04H74	GWN04LPW	GWN04P7K	GWN04T7N	GWN050WG
GWN04EL8	GWN04H75	GWN04LR0	GWN04P7L	GWN04T7P	GWN050WH
GWN04EL9	GWN04H76	GWN04LR1	GWN04P7M	GWN04T7R	GWN050WJ
GWN04ELA	GWN04H77	GWN04LR2	GWN04P7N	GWN04T7T	GWN050WK
GWN04ELC	GWN04H78	GWN04LR5	GWN04P7P	GWN04TRC	GWN050WM
GWN04ELD	GWN04H79	GWN04LR7	GWN04P7R	GWN04TRD	GWN050WN
GWN04ELE	GWN04H7A	GWN04LR8	GWN04P7T	GWN04TRE	GWN050WP
GWN04ELF	GWN04H7C	GWN04LR9	GWN04PAC	GWN04TRF	GWN050WR
GWN04ELG	GWN04J9A	GWN04LRC	GWN04PAD	GWN04TRG	GWN050WT
GWN04ELH	GWN04J9C	GWN04LRE	GWN04PAE	GWN04W35	GWN050WW
GWN04ELJ	GWN04J9D	GWN04LRG	GWN04PAF	GWN04W38	GWN05100
GWN04EN1	GWN04J9E	GWN04LRJ	GWN04PFL	GWN04W3D	GWN05101
GWN04ERK	GWN04J9F	GWN04LRK	GWN04PFM	GWN04W3E	GWN05102
GWN04ERL	GWN04J9G	GWN04LRL	GWN04PFN	GWN04W3F	GWN05103
GWN04FT8	GWN04J9H	GWN04LRM	GWN04PFP	GWN04W3G	GWN05104
GWN04FT9	GWN04J9J	GWN04LRN	GWN04PFR	GWN04W3H	GWN05105
GWN04FTA	GWN04J9K	GWN04LRP	GWN04PFT	GWN04W3J	GWN05106
GWN04FTC	GWN04J9L	GWN04LRR	GWN04PFW	GWN04W3K	GWN051MJ
GWN04FTD	GWN04J9M	GWN04LRT	GWN04PGO	GWN04W3L	GWN051MK
GWN04FTE	GWN04J9N	GWN04LRW	GWN04PRG	GWN04W3M	GWN051ML
GWN04FTF	GWN04J9P	GWN04LTO	GWN04PRH	GWN04W3N	GWN0525N
GWN04FTG	GWN04J9R	GWN04LT2	GWN04PRJ	GWN04W3P	GWN0525P
GWN04FTH	GWN04J9T	GWN04N1D	GWN04PRK	GWN04W3R	GWN0525R
GWN04GNA	GWN04J9W	GWN04N1F	GWN04PRL	GWN04W3T	GWN0525T
GWN04GNC	GWN04JA0	GWN04N1H	GWN04RHL	GWN04W3W	GWN0525W
GWN04GND	GWN04JA1	GWN04N1J	GWN04RHM	GWN04W40	GWN05260
GWN04GNE	GWN04LJ4	GWN04N1L	GWN04RHN	GWN04W41	GWN05261
GWN04GNF	GWN04LJ5	GWN04N1M	GWN04RHP	GWN04W42	GWN05262
GWN04GNG	GWN04LJ6	GWN04N40	GWN04RHR	GWN04W43	GWN05263
GWN04GNH	GWN04LJ7	GWN04N41	GWN04RW8	GWN04WL6	GWN05264
GWN04GNJ	GWN04LJ8	GWN04N42	GWN04RW9	GWN04WL7	GWN05265
GWN04GNK	GWN04LJ9	GWN04N43	GWN04RWA	GWN04WL8	GWN05266
GWN04GNL	GWN04LJA	GWN04N44	GWN04RWC	GWN04WL9	GWN052AW
GWN04GNM	GWN04LJC	GWN04NA6	GWN04RWD	GWN04WLA	GWN052C0
GWN04GNN	GWN04LJD	GWN04NA7	GWN04RWE	GWN04WLD	GWN052C1
GWN04GNP	GWN04LJE	GWN04NA8	GWN04RWF	GWN04WLE	GWN052C2
GWN04GNR	GWN04LPA	GWN04NA9	GWN04RWG	GWN04WLF	GWN052C3
GWN04GNT	GWN04LPC	GWN04NAA	GWN04T05	GWN04WLG	GWN052C4
GWN04GNW	GWN04LPD	GWN04P7A	GWN04T7E	GWN04WLH	GWN052C5
GWN04GP0	GWN04LPE	GWN04P7C	GWN04T7F	GWN05011	GWN052C7
GWN04GP1	GWN04LPF	GWN04P7D	GWN04T7G	GWN05012	GWN05337
GWN04H6W	GWN04LPG	GWN04P7E	GWN04T7H	GWN05013	GWN0537P
GWN04H70	GWN04LPH	GWN04P7F	GWN04T7J	GWN050MP	GWN0537R
GWN04H71	GWN04LPJ	GWN04P7G	GWN04T7K	GWN050MR	GWN0537T
GWN04H72	GWN04LPN	GWN04P7H	GWN04T7L	GWN050MT	GWN0537W
GWN04H73	GWN04LPR	GWN04P7J	GWN04T7M	GWN050MW	GWN05380





## Appendix 2 – P/N 1795M36P02 – Affected Serial Numbers

GWN053G6	GWN0562G	GWN05857	GWN05APG	GWN05E9F	GWN05GTL
GWN053G7	GWN0562H	GWN05858	GWN05APH	GWN05E9G	GWN05GTN
GWN053G8	GWN0562J	GWN05859	GWN05CC9	GWN05EE9	GWN05GTP
GWN053G9	GWN0562K	GWN0585A	GWN05CDL	GWN05EEA	GWN05HDE
GWN053GA	GWN0566T	GWN0585C	GWN05CDM	GWN05EEC	GWN05HDF
GWN053GC	GWN0566W	GWN058RA	GWN05CDN	GWN05EED	GWN05HDG
GWN053GD	GWN05670	GWN058RC	GWN05CDP	GWN05EEE	GWN05HDH
GWN053GE	GWN05671	GWN058RD	GWN05CDR	GWN05EEG	GWN05HDJ
GWN053GF	GWN05672	GWN058RE	GWN05CDT	GWN05EMK	GWN05HDK
GWN053WL	GWN05673	GWN058RF	GWN05CDW	GWN05EML	GWN05HDL
GWN053WN	GWN056F9	GWN058RG	GWN05CE0	GWN05EMN	GWN05HDM
GWN053WP	GWN056FA	GWN058RH	GWN05CE1	GWN05EMP	GWN05HDN
GWN053WR	GWN056FC	GWN058RJ	GWN05CE2	GWN05EMR	GWN05J19
GWN053WT	GWN056FD	GWN05974	GWN05CNK	GWN05EW2	GWN05J1A
GWN053WW	GWN056JT	GWN05975	GWN05CNL	GWN05EW3	GWN05J1D
GWN05400	GWN056JW	GWN05976	GWN05CNM	GWN05EW4	GWN05J1E
GWN05401	GWN056K0	GWN059J6	GWN05CNN	GWN05EW6	GWN05J1F
GWN05402	GWN056K1	GWN059J7	GWN05CNP	GWN05F2F	GWN05J1G
GWN054LL	GWN056W4	GWN059J8	GWN05CNR	GWN05F2G	GWN05J1H
GWN054LM	GWN056W5	GWN059J9	GWN05CNT	GWN05F2H	GWN05JFE
GWN054LN	GWN056W7	GWN059JA	GWN05CNW	GWN05F2J	GWN05JFF
GWN054LP	GWN056W8	GWN059JC	GWN05CP0	GWN05F2K	GWN05JFG
GWN054LR	GWN056W9	GWN059JD	GWN05CP1	GWN05F2L	GWN05JFH
GWN054LT	GWN05763	GWN059JE	GWN05D3D	GWN05FJF	GWN05JFJ
GWN054LW	GWN05764	GWN059JF	GWN05D3E	GWN05FJG	GWN05JFK
GWN054M0	GWN05765	GWN059JJ	GWN05D3F	GWN05FJJ	GWN05JFL
GWN054M1	GWN05766	GWN05A4F	GWN05D3G	GWN05FJK	GWN05JFM
GWN054M2	GWN057H4	GWN05A4G	GWN05D3H	GWN05FPC	GWN05JRE
GWN05507	GWN057H5	GWN05A4H	GWN05D3J	GWN05FPD	GWN05JRF
GWN05508	GWN057H6	GWN05A4J	GWN05D3K	GWN05FPE	GWN05JRG
GWN05509	GWN057H7	GWN05A4K	GWN05D3L	GWN05FPF	GWN05JRH
GWN0550A	GWN057HP	GWN05A4L	GWN05D3M	GWN05G45	GWN05JRJ
GWN0557R	GWN057HR	GWN05AGJ	GWN05D3N	GWN05GD8	GWN05K0J
GWN0557T	GWN05831	GWN05AGK	GWN05DF8	GWN05GD9	GWN05K0K
GWN0557W	GWN05832	GWN05AGL	GWN05DF9	GWN05GDA	GWN05K0L
GWN05580	GWN05833	GWN05AGM	GWN05DFA	GWN05GDC	GWN05K7R
GWN05581	GWN05834	GWN05AGN	GWN05E7H	GWN05GDD	GWN05K7T
GWN05582	GWN05835	GWN05AGP	GWN05E7J	GWN05GE5	GWN05K7W
GWN055PP	GWN0584W	GWN05AP7	GWN05E7K	GWN05GE6	GWN05K80
GWN055PR	GWN05850	GWN05AP8	GWN05E7L	GWN05GE7	GWN05K81
GWN055PT	GWN05851	GWN05AP9	GWN05E7M	GWN05GE8	GWN05KJ6
GWN055PW	GWN05852	GWN05APA	GWN05E7N	GWN05GE9	GWN05KJ7
GWN055R0	GWN05853	GWN05APC	GWN05E7P	GWN05GN1	GWN05KJ8
GWN055R1	GWN05854	GWN05APD	GWN05E9C	GWN05GN2	GWN05KJ9
GWN055R2	GWN05855	GWN05APE	GWN05E9D	GWN05GN3	GWN05L46
GWN055R3	GWN05856	GWN05APF	GWN05E9E	GWN05GTK	GWN05L47



## Appendix 2 – P/N 1795M36P02 – Affected Serial Numbers

GWN05L48	GWN05PMF	GWN05WW5	GWN0622H	GWN0678W	GWN06C11
GWN05LC3	GWN05PMG	GWN05WW6	GWN0622J	GWN06790	GWN06C12
GWN05LC4	GWN05PMH	GWN05WW7	GWN062PJ	GWN06791	GWN06C13
GWN05LC5	GWN05PMJ	GWN05WW8	GWN062PK	GWN067PK	GWN06C14
GWN05LC6	GWN05PMK	GWN05WW9	GWN062PL	GWN067PR	GWN06C15
GWN05LC7	GWN05PML	GWN06001	GWN062PM	GWN067R2	GWN06C16
GWN05LRC	GWN05PMM	GWN06002	GWN062PN	GWN067R3	GWN06C17
GWN05LRD	GWN05R85	GWN06003	GWN0633R	GWN067R4	GWN06C18
GWN05LRE	GWN05R86	GWN06004	GWN0633T	GWN067RT	GWN06C19
GWN05LRF	GWN05R87	GWN06005	GWN0633W	GWN0686C	GWN06CGA
GWN05LRG	GWN05R89	GWN06006	GWN06340	GWN0686D	GWN06CGC
GWN05M32	GWN05R8C	GWN06007	GWN06341	GWN0686E	GWN06CGD
GWN05M33	GWN05R8D	GWN0606R	GWN06342	GWN0686F	GWN06CGE
GWN05M34	GWN05RR0	GWN0606T	GWN06343	GWN0686G	GWN06CGF
GWN05M35	GWN05RR3	GWN060F2	GWN06375	GWN0686H	GWN06CGG
GWN05M36	GWN05RR5	GWN060F3	GWN06376	GWN0686J	GWN06CGH
GWN05M66	GWN05RR6	GWN060F4	GWN06377	GWN0686K	GWN06CGJ
GWN05M67	GWN05RR7	GWN060F5	GWN06378	GWN0686L	GWN06CGK
GWN05M68	GWN05T1T	GWN060F6	GWN06379	GWN0693C	GWN06CGL
GWN05M69	GWN05T1W	GWN060L4	GWN0637A	GWN0693D	GWN06CGM
GWN05M6A	GWN05T20	GWN060L5	GWN0637C	GWN0693E	GWN06CGN
GWN05MAM	GWN05T21	GWN060L6	GWN0637D	GWN0693F	GWN06CGP
GWN05MAN	GWN05T22	GWN060L7	GWN0637E	GWN0693G	GWN06CGR
GWN05MAP	GWN05T23	GWN06122	GWN0637F	GWN069LR	GWN06D84
GWN05MAR	GWN05TFW	GWN06123	GWN0637G	GWN069LT	GWN06D85
GWN05MAT	GWN05TG0	GWN06124	GWN0637H	GWN069LW	GWN06D86
GWN05MAW	GWN05TG1	GWN06125	GWN0637J	GWN069M0	GWN06D87
GWN05MC0	GWN05TG2	GWN06126	GWN06416	GWN069M1	GWN06D88
GWN05MC1	GWN05TG3	GWN06127	GWN06417	GWN069M2	GWN06D89
GWN05N58	GWN05TJ8	GWN06128	GWN06418	GWN06A0K	GWN06D8A
GWN05N59	GWN05TJ9	GWN06129	GWN06419	GWN06A0L	GWN06DKL
GWN05N5A	GWN05TJA	GWN0612A	GWN066E7	GWN06A0M	GWN06DKM
GWN05N5C	GWN05TJC	GWN0612C	GWN066E8	GWN06A0N	GWN06DKN
GWN05N5D	GWN05TJD	GWN061N7	GWN066E9	GWN06ACF	GWN06DKP
GWN05N5E	GWN05W8K	GWN061N8	GWN066EA	GWN06ACG	GWN06DKT
GWN05N5F	GWN05W8M	GWN061N9	GWN066N1	GWN06ACH	GWN06DKW
GWN05NFH	GWN05W8N	GWN061NC	GWN066N3	GWN06ACJ	GWN06DL0
GWN05NFJ	GWN05W8P	GWN061ND	GWN066N4	GWN06ACK	GWN06DL1
GWN05NFK	GWN05W8R	GWN061NE	GWN066N6	GWN06ACL	GWN06E30
GWN05NMG	GWN05W8T	GWN061NF	GWN066N7	GWN06ACM	GWN06E31
GWN05NMH	GWN05WC0	GWN0622A	GWN066N8	GWN06AKA	GWN06E32
GWN05NMJ	GWN05WC1	GWN0622C	GWN066N9	GWN06AKC	GWN06E33
GWN05PM3	GWN05WC2	GWN0622D	GWN0678N	GWN06AKD	GWN06E34
GWN05PMC	GWN05WC3	GWN0622E	GWN0678P	GWN06AKE	GWN06E35
GWN05PMD	GWN05WC4	GWN0622F	GWN0678R	GWN06AKF	GWN06E36
GWN05PME	GWN05WC5	GWN0622G	GWN0678T	GWN06AKG	GWN06E9J



## Appendix 2 – P/N 1795M36P02 – Affected Serial Numbers

GWN06EJN	GWN06H6T	GWN06KM7	GWN06NT6	GWN06T2A	GWN071E9
GWN06EJP	GWN06H6W	GWN06KMA	GWN06NT7	GWN06T2C	GWN071EA
GWN06EJR	GWN06H70	GWN06KMD	GWN06NT8	GWN06W1K	GWN071ED
GWN06EJT	GWN06H71	GWN06KME	GWN06NT9	GWN06W1M	GWN071EE
GWN06EJW	GWN06H72	GWN06KMG	GWN06NTA	GWN06W1N	GWN071EF
GWN06EK0	GWN06H73	GWN06L41	GWN06NTC	GWN06W1P	GWN071EG
GWN06EK1	GWN06HG6	GWN06L42	GWN06NTK	GWN06W1R	GWN071EH
GWN06ETF	GWN06HG7	GWN06L43	GWN06P5C	GWN06W1T	GWN071EJ
GWN06ETG	GWN06HG8	GWN06L44	GWN06P5D	GWN06W24	GWN071EK
GWN06ETH	GWN06HG9	GWN06L45	GWN06P5E	GWN06W25	GWN071EL
GWN06ETJ	GWN06HGA	GWN06L46	GWN06P5F	GWN06W26	GWN071EM
GWN06FJ5	GWN06HGC	GWN06LN2	GWN06PPK	GWN06W28	GWN071EN
GWN06FJ6	GWN06HGD	GWN06LN3	GWN06PPL	GWN06W29	GWN071EP
GWN06FJ7	GWN06HGE	GWN06LN4	GWN06PPM	GWN06W2A	GWN071ER
GWN06FJ8	GWN06HWA	GWN06LN5	GWN06PPN	GWN06W2C	GWN0723E
GWN06FJ9	GWN06HWC	GWN06LN6	GWN06PPP	GWN06W2D	GWN0723F
GWN06FJA	GWN06HWD	GWN06LWE	GWN06PPR	GWN06W2E	GWN0723G
GWN06FJC	GWN06HWE	GWN06LWF	GWN06PPT	GWN06WDP	GWN0723H
GWN06FJD	GWN06HWF	GWN06LWG	GWN06PWL	GWN06WDR	GWN0723J
GWN06FR6	GWN06J4K	GWN06LWH	GWN06R77	GWN06WDT	GWN072AF
GWN06FR7	GWN06J4L	GWN06LWJ	GWN06R78	GWN06WDW	GWN072AG
GWN06FR8	GWN06J4M	GWN06LWK	GWN06R79	GWN06WE0	GWN072AH
GWN06FR9	GWN06J4N	GWN06M6K	GWN06R7A	GWN06WE1	GWN072AJ
GWN06FRA	GWN06J4P	GWN06M6L	GWN06R7C	GWN06WE2	GWN072AK
GWN06FRC	GWN06J4R	GWN06M6M	GWN06R7D	GWN06WE3	GWN072LC
GWN06FRD	GWN06JPE	GWN06M6N	GWN06R7E	GWN06WRJ	GWN072LD
GWN06G3M	GWN06JPG	GWN06MGW	GWN06R7F	GWN06WRK	GWN072LE
GWN06G3N	GWN06JPH	GWN06MH0	GWN06R7H	GWN06WRL	GWN072LF
GWN06G3P	GWN06JPJ	GWN06MH1	GWN06R7J	GWN06WRM	GWN072LG
GWN06G3R	GWN06JPK	GWN06MH2	GWN06R7K	GWN06WRN	GWN072LH
GWN06G3T	GWN06K3T	GWN06MH3	GWN06RGR	GWN0704A	GWN072LJ
GWN06GH4	GWN06K40	GWN06MH4	GWN06RGW	GWN0704C	GWN072WK
GWN06GH5	GWN06K41	GWN06MH5	GWN06RH0	GWN0704D	GWN0736G
GWN06GH6	GWN06K42	GWN06N0N	GWN06RPF	GWN0704E	GWN0736H
GWN06GH7	GWN06K70	GWN06N0P	GWN06RPG	GWN0704F	GWN0736J
GWN06GH8	GWN06K71	GWN06N0R	GWN06RPH	GWN0704H	GWN0736K
GWN06GH9	GWN06K72	GWN06N0T	GWN06RPJ	GWN0704J	GWN0736L
GWN06GKG	GWN06K73	GWN06N0W	GWN06RPK	GWN070A6	GWN0736M
GWN06GKH	GWN06K74	GWN06N10	GWN06T22	GWN070A7	GWN0736N
GWN06H2A	GWN06K80	GWN06NA4	GWN06T23	GWN070A8	GWN0736P
GWN06H2C	GWN06K81	GWN06NA5	GWN06T24	GWN070A9	GWN0736R
GWN06H2D	GWN06K82	GWN06NA6	GWN06T25	GWN070AA	GWN073N3
GWN06H2E	GWN06K83	GWN06NA7	GWN06T26	GWN070AC	GWN073N5
GWN06H2F	GWN06K84	GWN06NA8	GWN06T27	GWN070AD	GWN073N7
GWN06H2G	GWN06K85	GWN06NA9	GWN06T28	GWN071E7	GWN073NC
GWN06H2H	GWN06K86	GWN06NT5	GWN06T29	GWN071E8	GWN073NF



## Appendix 2 – P/N 1795M36P02 – Affected Serial Numbers

GWN073NG	GWN076N6	GWN079F3	GWN07DJ0	GWN07FR2	GWN07HM6
GWN073NH	GWN076N7	GWN079F4	GWN07DL6	GWN07FR3	GWN07HM7
GWN0742J	GWN076N8	GWN079F5	GWN07DL7	GWN07FR5	GWN07HM8
GWN0742K	GWN076N9	GWN079F6	GWN07DL8	GWN07G33	GWN07HM9
GWN0742L	GWN076NA	GWN079F7	GWN07DL9	GWN07G34	GWN07HMA
GWN0742M	GWN076NC	GWN079F8	GWN07DLA	GWN07G35	GWN07HMC
GWN0742N	GWN076ND	GWN079F9	GWN07DLD	GWN07G36	GWN07J38
GWN0742P	GWN076NE	GWN079FA	GWN07DLE	GWN07G37	GWN07J39
GWN074JJ	GWN076NF	GWN079FC	GWN07DLF	GWN07GF0	GWN07J3A
GWN074JK	GWN076NG	GWN079FD	GWN07DLG	GWN07GF1	GWN07J3C
GWN074JL	GWN0770J	GWN079FE	GWN07DLH	GWN07GF2	GWN07JP3
GWN074JN	GWN0770K	GWN079FF	GWN07DLJ	GWN07GF3	GWN07JP4
GWN074JP	GWN0770L	GWN07AE2	GWN07DLK	GWN07GF4	GWN07JP5
GWN074JR	GWN0770M	GWN07AE3	GWN07DLL	GWN07GF5	GWN07JP6
GWN074JT	GWN0776G	GWN07AE4	GWN07DLM	GWN07GF6	GWN07JP7
GWN074JW	GWN077M4	GWN07AE5	GWN07DLN	GWN07GF7	GWN07JP8
GWN074K0	GWN077M5	GWN07AE6	GWN07DRN	GWN07GF8	GWN07K0C
GWN074RK	GWN077M6	GWN07AE8	GWN07ECL	GWN07GF9	GWN07K0D
GWN074RL	GWN077M7	GWN07AE9	GWN07ECM	GWN07GTT	GWN07K0E
GWN074RM	GWN077M8	GWN07AEA	GWN07ECN	GWN07GTW	GWN07K0F
GWN074RN	GWN077M9	GWN07AEC	GWN07ECP	GWN07GW0	GWN07K1J
GWN074RP	GWN077MA	GWN07AED	GWN07EME	GWN07GW1	GWN07K1K
GWN074RR	GWN077MC	GWN07AEE	GWN07EMF	GWN07GW2	GWN07K1L
GWN074RT	GWN077MD	GWN07AEF	GWN07EMG	GWN07GW3	GWN07K1M
GWN074RW	GWN078AK	GWN07AEH	GWN07EMH	GWN07GW4	GWN07K1N
GWN0757A	GWN078AL	GWN07AEN	GWN07EMJ	GWN07GW5	GWN07K1P
GWN0757C	GWN078AM	GWN07C6L	GWN07EMK	GWN07GW6	GWN07K1R
GWN0757D	GWN078AN	GWN07C6M	GWN07EML	GWN07GW7	GWN07K1T
GWN0757E	GWN078AP	GWN07C6N	GWN07F07	GWN07H59	GWN07K1W
GWN0757F	GWN078NJ	GWN07C6R	GWN07F08	GWN07H5A	GWN07K20
GWN0757H	GWN078NK	GWN07C6T	GWN07F09	GWN07H5C	GWN07K21
GWN075M1	GWN078NL	GWN07C6W	GWN07F0A	GWN07H5D	GWN07K22
GWN075M2	GWN078NM	GWN07C70	GWN07F0C	GWN07H5E	GWN07K23
GWN075M3	GWN078NN	GWN07C71	GWN07F0D	GWN07H5F	GWN07K24
GWN075M4	GWN0790N	GWN07C72	GWN07F0E	GWN07H5G	GWN07K25
GWN075M5	GWN0790P	GWN07CT5	GWN07F0F	GWN07H5H	GWN07KJL
GWN0764G	GWN0790R	GWN07CT6	GWN07F7T	GWN07HDH	GWN07KJM
GWN0764H	GWN0790W	GWN07CT7	GWN07F7W	GWN07HDJ	GWN07KJN
GWN0764J	GWN07917	GWN07CT8	GWN07F80	GWN07HDK	GWN07KJP
GWN0764K	GWN0791A	GWN07CT9	GWN07F81	GWN07HDL	GWN07KJW
GWN0764L	GWN0791C	GWN07CTA	GWN07F82	GWN07HDM	GWN07KM8
GWN0764M	GWN0791D	GWN07CTC	GWN07FPR	GWN07HDN	GWN07KM9
GWN0764N	GWN0791E	GWN07DHP	GWN07FPT	GWN07HM2	GWN07KMA
GWN076N3	GWN079F0	GWN07DHR	GWN07FPW	GWN07HM3	GWN07KMC
GWN076N4	GWN079F1	GWN07DHT	GWN07FR0	GWN07HM4	GWN07KMD
GWN076N5	GWN079F2	GWN07DHW	GWN07FR1	GWN07HM5	GWN07KME



## Appendix 2 – P/N 1795M36P02 – Affected Serial Numbers

GWN07KMF	GWN07NW8	GWN07WM4	GWN082R2	GWN085H6	GWN088N6
GWN07KMG	GWN07NW9	GWN07WM5	GWN082WG	GWN085H7	GWN088N7
GWN07L18	GWN07PH5	GWN07WM6	GWN082WH	GWN085H8	GWN088N8
GWN07L19	GWN07PH6	GWN07WM7	GWN082WJ	GWN085R4	GWN088N9
GWN07L1A	GWN07PH7	GWN07WM8	GWN082WK	GWN085R5	GWN088NA
GWN07L1E	GWN07PH8	GWN07WM9	GWN082WL	GWN085R6	GWN088NC
GWN07LH1	GWN07PH9	GWN0805H	GWN082WM	GWN085R7	GWN0896G
GWN07LH2	GWN07PN6	GWN0805J	GWN082WN	GWN085R8	GWN0896H
GWN07LH3	GWN07PN7	GWN0805K	GWN082WP	GWN085R9	GWN0896J
GWN07LH4	GWN07PN8	GWN0805L	GWN082WR	GWN086G7	GWN0896K
GWN07LH5	GWN07PN9	GWN0805M	GWN083KK	GWN086G8	GWN0896L
GWN07LH6	GWN07PNA	GWN0805N	GWN083KL	GWN086G9	GWN0896M
GWN07M81	GWN07PNC	GWN080C2	GWN083KM	GWN086GA	GWN0896N
GWN07M82	GWN07R4W	GWN080C3	GWN083KN	GWN086GC	GWN0896O
GWN07M83	GWN07R50	GWN080C4	GWN083KP	GWN086MA	GWN0896P
GWN07M84	GWN07R51	GWN080C5	GWN083KR	GWN086MC	GWN0896Q
GWN07M85	GWN07R52	GWN080C6	GWN083KT	GWN086MD	GWN0896R
GWN07M86	GWN07R53	GWN080C7	GWN0840D	GWN086ME	GWN0896S
GWN07MFR	GWN07R54	GWN080C8	GWN0840E	GWN086TM	GWN0896T
GWN07MFT	GWN07R55	GWN080C9	GWN0840F	GWN086TN	GWN0896U
GWN07MFW	GWN07RDE	GWN080CA	GWN0840G	GWN086TP	GWN0896V
GWN07MG0	GWN07RDF	GWN0817G	GWN0840H	GWN086TR	GWN0896W
GWN07MG1	GWN07RDG	GWN0817H	GWN0840C0	GWN086TT	GWN0896X
GWN07MG2	GWN07RDH	GWN0817J	GWN0840C1	GWN086TW	GWN0896Y
GWN07N8R	GWN07RDJ	GWN0817K	GWN0840C2	GWN087L9	GWN0896Z
GWN07N8T	GWN07RDK	GWN0817L	GWN0840C3	GWN087LA	GWN0896A
GWN07N8W	GWN07RDL	GWN0817M	GWN0840C8	GWN087LC	GWN0896B
GWN07N90	GWN07RDM	GWN0817N	GWN084FD	GWN087LD	GWN0896C
GWN07N9L	GWN07RTJ	GWN0817P	GWN084FE	GWN087LE	GWN0896D
GWN07N9P	GWN07RTK	GWN081LE	GWN084FF	GWN087LF	GWN0896E
GWN07N9R	GWN07RTM	GWN081LF	GWN084FG	GWN087LG	GWN0896F
GWN07N9T	GWN07RTN	GWN081LG	GWN084FP	GWN087LH	GWN0896G
GWN07N9W	GWN07RTP	GWN081LH	GWN084PT	GWN087W1	GWN0896H
GWN07NA0	GWN07T86	GWN082AJ	GWN084PW	GWN087W2	GWN0896I
GWN07NA1	GWN07T87	GWN082AK	GWN084R0	GWN087W3	GWN0896J
GWN07NA4	GWN07T88	GWN082AL	GWN084R1	GWN087W4	GWN0896K
GWN07NA7	GWN07W8J	GWN082AM	GWN084R3	GWN087W5	GWN0896L
GWN07NA9	GWN07W8K	GWN082AN	GWN084R4	GWN087W6	GWN0896M
GWN07NW0	GWN07W8L	GWN082AP	GWN0857F	GWN088J9	GWN0896N
GWN07NW1	GWN07W8M	GWN082AR	GWN0857G	GWN088JA	GWN0896O
GWN07NW2	GWN07W8N	GWN082AT	GWN0857H	GWN088JC	GWN0896P
GWN07NW3	GWN07W8P	GWN082PR	GWN0857J	GWN088JD	GWN0896Q
GWN07NW4	GWN07W8R	GWN082PT	GWN085H2	GWN088JE	GWN0896R
GWN07NW5	GWN07W8T	GWN082PW	GWN085H3	GWN088JF	GWN0896S
GWN07NW6	GWN07W8W	GWN082R0	GWN085H4	GWN088JG	GWN0896T
GWN07NW7	GWN07W90	GWN082R1	GWN085H5	GWN088JH	GWN0896U



## Appendix 2 – P/N 1795M36P02 – Affected Serial Numbers

GWN08C6J	GWN08F2N	GWN08H5P	GWN08KMN	GWN08NK2	GWN08T4J
GWN08C6K	GWN08F2P	GWN08HF3	GWN08KMP	GWN08NK3	GWN08T4K
GWN08C6L	GWN08FCT	GWN08HF4	GWN08KMR	GWN08NK4	GWN08T4L
GWN08C6M	GWN08FCW	GWN08HF5	GWN08KW7	GWN08NK5	GWN08T4M
GWN08C6N	GWN08FD0	GWN08HF6	GWN08KW8	GWN08NK6	GWN08TJ0
GWN08C6P	GWN08FD1	GWN08HF7	GWN08KWA	GWN08NK7	GWN08TJ1
GWN08C6R	GWN08FD2	GWN08HF8	GWN08KWC	GWN08NK8	GWN08TJN
GWN08C6T	GWN08FD3	GWN08J0P	GWN08KWD	GWN08NK9	GWN08TJP
GWN08CK9	GWN08FJN	GWN08J0R	GWN08LAK	GWN08NKA	GWN08TJR
GWN08CKA	GWN08FJP	GWN08J0T	GWN08LAL	GWN08NKC	GWN08TJT
GWN08CKC	GWN08FJR	GWN08J0W	GWN08LAM	GWN08NKD	GWN08W82
GWN08CKD	GWN08FJT	GWN08J10	GWN08LAN	GWN08NKE	GWN08W83
GWN08CKE	GWN08FJW	GWN08J11	GWN08LAP	GWN08NKF	GWN08W84
GWN08CPC	GWN08FK0	GWN08J4D	GWN08LAR	GWN08NKG	GWN08W85
GWN08CPD	GWN08FLO	GWN08J4E	GWN08LMT	GWN08NKH	GWN08W86
GWN08CPE	GWN08FL1	GWN08J4F	GWN08LMW	GWN08NTT	GWN08W87
GWN08CPF	GWN08FL2	GWN08J4G	GWN08LN0	GWN08NTW	GWN08WN0
GWN08CPG	GWN08FL3	GWN08J4H	GWN08LN2	GWN08NW0	GWN08WN1
GWN08CPH	GWN08FL4	GWN08J4J	GWN08LN3	GWN08NW1	GWN08WN2
GWN08DD6	GWN08FL5	GWN08JD6	GWN08LN4	GWN08NW2	GWN08WN3
GWN08DD7	GWN08FL6	GWN08JD7	GWN08LN5	GWN08NW3	GWN08WN4
GWN08DD8	GWN08G2T	GWN08JD8	GWN08M5E	GWN08NW4	GWN08WN5
GWN08DD9	GWN08G2W	GWN08JD9	GWN08M5F	GWN08P31	GWN0903K
GWN08DDA	GWN08G30	GWN08JDA	GWN08M5G	GWN08P32	GWN0903M
GWN08DDC	GWN08G31	GWN08JDC	GWN08M5H	GWN08P33	GWN0903N
GWN08DRF	GWN08G33	GWN08JDD	GWN08M5J	GWN08PHA	GWN0903P
GWN08DRG	GWN08GHM	GWN08JND	GWN08M5K	GWN08PHC	GWN0903R
GWN08DRH	GWN08GHN	GWN08JNE	GWN08MR9	GWN08PHD	GWN0903T
GWN08DRJ	GWN08GHP	GWN08JNF	GWN08MRA	GWN08PHE	GWN0903W
GWN08DRK	GWN08GHR	GWN08JNG	GWN08MRC	GWN08PHF	GWN0904A
GWN08DRL	GWN08GHT	GWN08JNH	GWN08MRD	GWN08PHG	GWN090D0
GWN08E7J	GWN08GHW	GWN08K5M	GWN08MRE	GWN08PHH	GWN090D1
GWN08E7K	GWN08GWE	GWN08K5N	GWN08MRF	GWN08R31	GWN090D2
GWN08E7L	GWN08GWF	GWN08K5P	GWN08MRG	GWN08R32	GWN090D3
GWN08E7M	GWN08GWG	GWN08K5R	GWN08MRH	GWN08R33	GWN090D4
GWN08E7N	GWN08GWH	GWN08K5T	GWN08N5N	GWN08R34	GWN090D5
GWN08E7P	GWN08GWJ	GWN08K5W	GWN08N5P	GWN08R35	GWN090D6
GWN08EK7	GWN08GWK	GWN08KEK	GWN08N5R	GWN08R36	GWN090G5
GWN08EK8	GWN08GWL	GWN08KER	GWN08N5T	GWN08RT8	GWN090G6
GWN08EK9	GWN08H5F	GWN08KET	GWN08N5W	GWN08RT9	GWN090G8
GWN08EKA	GWN08H5H	GWN08KEW	GWN08N60	GWN08RTA	GWN090GA
GWN08EKC	GWN08H5J	GWN08KF0	GWN08ND5	GWN08RTC	GWN090GE
GWN08F2J	GWN08H5K	GWN08KF1	GWN08ND6	GWN08RTD	GWN090GH
GWN08F2K	GWN08H5L	GWN08KMK	GWN08ND8	GWN08RTE	GWN090K5
GWN08F2L	GWN08H5M	GWN08KML	GWN08ND9	GWN08T4G	GWN090K6
GWN08F2M	GWN08H5N	GWN08KMM	GWN08NDA	GWN08T4H	GWN090K7



## Appendix 2 – P/N 1795M36P02 – Affected Serial Numbers

GWN090K8	GWN0941K	GWN09785	GWNDT733	GWNDY723	GWNGB184
GWN090K9	GWN0941L	GWN09786	GWNDT734	GWNDY724	GWNGB185
GWN090KA	GWN0941M	GWN09787	GWNDT735	GWNDY725	GWNGB215
GWN090P8	GWN094LA	GWN0987G	GWNDT736	GWNGA002	GWNGB216
GWN090P9	GWN094LC	GWN0987H	GWNDT737	GWNGA003	GWNGB217
GWN090PA	GWN094LD	GWN0987J	GWNDT738	GWNGA004	GWNGB218
GWN09230	GWN094LE	GWN0987K	GWNDT739	GWNGA005	GWNGB219
GWN09231	GWN094LF	GWN0987L	GWNDT740	GWNGA006	GWNGB220
GWN09232	GWN094LG	GWN0987M	GWNDT742	GWNGA227	GWNGB221
GWN09233	GWN094LH	GWN098A2	GWNDT743	GWNGA228	GWNGB270
GWN09234	GWN094LJ	GWN098A3	GWNDT744	GWNGA230	GWNGB272
GWN09235	GWN094PM	GWN098A4	GWNDT745	GWNGA231	GWNGB273
GWN0923C	GWN094PN	GWN098A5	GWNDT775	GWNGA279	GWNGB274
GWN0923D	GWN094PP	GWN098A6	GWNDT776	GWNGA280	GWNGB275
GWN0923E	GWN094PR	GWN098W7	GWNDT777	GWNGA281	GWNGB303
GWN0923F	GWN0951J	GWN098W9	GWNDT778	GWNGA282	GWNGB304
GWN0923G	GWN0951K	GWN098WC	GWNDY004	GWNGA400	GWNGB305
GWN092W8	GWN0951L	GWN098WD	GWNDY005	GWNGA401	GWNGB306
GWN092W9	GWN0951M	GWN0990F	GWNDY006	GWNGA402	GWNGB319
GWN092WA	GWN0961K	GWN0990H	GWNDY007	GWNGA403	GWNGB460
GWN092WC	GWN0961L	GWN0990J	GWNDY008	GWNGA404	GWNGB463
GWN092WD	GWN0961M	GWN0990L	GWNDY009	GWNGA405	GWNGB464
GWN092WE	GWN0961P	GWNDS720	GWNDY159	GWNGA418	GWNGB465
GWN092WF	GWN0961R	GWNDS721	GWNDY160	GWNGA552	GWNGB466
GWN0932N	GWN09689	GWNDS722	GWNDY161	GWNGA553	GWNGB468
GWN0932P	GWN0968A	GWNDS723	GWNDY162	GWNGA650	GWNGB725
GWN0932R	GWN0968C	GWNDS936	GWNDY163	GWNGA651	GWNGB726
GWN0932T	GWN0968D	GWNDS939	GWNDY164	GWNGA652	GWNGB727
GWN0932W	GWN0968E	GWNDS940	GWNDY165	GWNGA784	GWNGB728
GWN09330	GWN096C8	GWNDS941	GWNDY399	GWNGA785	GWNGB729
GWN09331	GWN096C9	GWNDS942	GWNDY400	GWNGA786	GWNGB730
GWN0939M	GWN096CA	GWNDS943	GWNDY401	GWNGA787	GWNGB731
GWN0939N	GWN096CC	GWNDT256	GWNDY402	GWNGA788	GWNGB732
GWN0939P	GWN096CD	GWNDT257	GWNDY403	GWNGA898	GWNGB733
GWN0939R	GWN0971C	GWNDT258	GWNDY404	GWNGA899	GWNGD021
GWN0939T	GWN0971D	GWNDT259	GWNDY405	GWNGA900	GWNGD022
GWN0939W	GWN0971F	GWNDT260	GWNDY406	GWNGA901	GWNGD023
GWN093A0	GWN0972R	GWNDT291	GWNDY622	GWNGB020	GWNGD024
GWN093A1	GWN0972T	GWNDT293	GWNDY623	GWNGB021	GWNGD025
GWN093J1	GWN0972W	GWNDT442	GWNDY624	GWNGB022	GWNGD117
GWN093J2	GWN09730	GWNDT443	GWNDY625	GWNGB024	GWNGD118
GWN093LE	GWN09731	GWNDT444	GWNDY626	GWNGB025	GWNGD119
GWN093LF	GWN09732	GWNDT729	GWNDY627	GWNGB026	GWNGD120
GWN093LG	GWN09782	GWNDT730	GWNDY628	GWNGB027	GWNGD121
GWN093LH	GWN09783	GWNDT731	GWNDY629	GWNGB028	GWNGD122
GWN0941J	GWN09784	GWNDT732	GWNDY722	GWNGB183	GWNGD123



## Appendix 2 – P/N 1795M36P02 – Affected Serial Numbers

GWNGD124	GWNGE545	GWNGF837	GWNGH071	GWNGH616	GWNGK077
GWNGD270	GWNGE546	GWNGF838	GWNGH072	GWNGH962	GWNGK078
GWNGD271	GWNGE631	GWNGF909	GWNGH073	GWNGH963	GWNGK079
GWNGD272	GWNGE632	GWNGG015	GWNGH074	GWNGH964	GWNGK110
GWNGD273	GWNGE633	GWNGG016	GWNGH075	GWNGH965	GWNGK111
GWNGD274	GWNGE634	GWNGG017	GWNGH076	GWNGH966	GWNGK112
GWNGD377	GWNGE733	GWNGG148	GWNGH077	GWNGH967	GWNGK113
GWNGD378	GWNGE748	GWNGG149	GWNGH078	GWNGH968	GWNGK114
GWNGD379	GWNGE749	GWNGG150	GWNGH079	GWNGH969	GWNGK115
GWNGD441	GWNGE750	GWNGG151	GWNGH080	GWNGH970	GWNGK116
GWNGD442	GWNGE751	GWNGG152	GWNGH081	GWNGH971	GWNGK117
GWNGD443	GWNGE752	GWNGG153	GWNGH082	GWNGH972	GWNGK118
GWNGD444	GWNGE753	GWNGG154	GWNGH083	GWNGH973	GWNGK119
GWNGD445	GWNGE754	GWNGG157	GWNGH135	GWNGJ072	GWNGK120
GWNGD446	GWNGE755	GWNGG158	GWNGH136	GWNGJ073	GWNGK121
GWNGD913	GWNGF216	GWNGG159	GWNGH137	GWNGJ074	GWNGK122
GWNGD914	GWNGF217	GWNGG160	GWNGH138	GWNGJ076	GWNGK123
GWNGD916	GWNGF218	GWNGG161	GWNGH139	GWNGJ077	GWNGK124
GWNGD917	GWNGF219	GWNGG185	GWNGH167	GWNGJ108	GWNGK125
GWNGD918	GWNGF220	GWNGG186	GWNGH168	GWNGJ109	GWNGK126
GWNGD919	GWNGF221	GWNGG537	GWNGH169	GWNGJ110	GWNGK127
GWNGD920	GWNGF222	GWNGG607	GWNGH170	GWNGJ112	GWNGK128
GWNGD921	GWNGF224	GWNGG608	GWNGH171	GWNGJ124	GWNGK129
GWNGD922	GWNGF356	GWNGG609	GWNGH258	GWNGJ125	GWNGK130
GWNGD923	GWNGF358	GWNGG636	GWNGH259	GWNGJ126	GWNGK131
GWNGD924	GWNGF359	GWNGG637	GWNGH260	GWNGJ127	GWNGK132
GWNGD925	GWNGF360	GWNGG638	GWNGH261	GWNGJ282	GWNGK133
GWNGD926	GWNGF362	GWNGG639	GWNGH262	GWNGJ283	GWNGK134
GWNGD927	GWNGF363	GWNGG640	GWNGH263	GWNGJ284	GWNGK135
GWNGD928	GWNGF523	GWNGG641	GWNGH340	GWNGJ286	GWNGK136
GWNGD929	GWNGF526	GWNGG642	GWNGH341	GWNGJ367	GWNGK274
GWNGE024	GWNGF527	GWNGG705	GWNGH342	GWNGJ368	GWNGK275
GWNGE025	GWNGF528	GWNGG706	GWNGH343	GWNGJ370	GWNGK276
GWNGE026	GWNGF529	GWNGG707	GWNGH344	GWNGJ371	GWNGK277
GWNGE084	GWNGF530	GWNGG708	GWNGH407	GWNGJ414	GWNGK280
GWNGE085	GWNGF531	GWNGG709	GWNGH408	GWNGJ415	GWNGK281
GWNGE086	GWNGF659	GWNGG711	GWNGH595	GWNGJ416	GWNGK282
GWNGE123	GWNGF826	GWNGG712	GWNGH596	GWNGJ417	GWNGK410
GWNGE124	GWNGF827	GWNGG713	GWNGH597	GWNGJ418	GWNGK411
GWNGE238	GWNGF828	GWNGG714	GWNGH598	GWNGJ419	GWNGK412
GWNGE239	GWNGF829	GWNGG715	GWNGH599	GWNGK071	GWNGK413
GWNGE240	GWNGF830	GWNGG786	GWNGH600	GWNGK072	GWNGK414
GWNGE241	GWNGF832	GWNGG787	GWNGH601	GWNGK073	GWNGK415
GWNGE490	GWNGF833	GWNGG788	GWNGH602	GWNGK074	GWNGK416
GWNGE543	GWNGF834	GWNGG789	GWNGH603	GWNGK075	GWNGK647
GWNGE544	GWNGF835	GWNGH070	GWNGH615	GWNGK076	GWNGK648





## Appendix 2 – P/N 1795M36P02 – Affected Serial Numbers

GWNGK649	GWNGL354	GWNGM359	GWNGN860	GWNGP097	GWNGP944
GWNGK651	GWNGL355	GWNGM360	GWNGN861	GWNGP098	GWNGP945
GWNGK652	GWNGL559	GWNGN020	GWNGN862	GWNGP099	GWNGP946
GWNGK653	GWNGL560	GWNGN021	GWNGN863	GWNGP100	GWNGS038
GWNGK654	GWNGL561	GWNGN022	GWNGN864	GWNGP101	GWNGS039
GWNGK655	GWNGL562	GWNGN023	GWNGN865	GWNGP102	GWNGS040
GWNGK656	GWNGL563	GWNGN024	GWNGN866	GWNGP233	GWNGS041
GWNGK702	GWNGL609	GWNGN032	GWNGN867	GWNGP234	GWNGS042
GWNGK730	GWNGL610	GWNGN172	GWNGN868	GWNGP235	GWNGS043
GWNGK731	GWNGL611	GWNGN173	GWNGN869	GWNGP236	GWNGS044
GWNGK732	GWNGL612	GWNGN174	GWNGN870	GWNGP237	GWNGS045
GWNGK733	GWNGL613	GWNGN175	GWNGN871	GWNGP238	GWNGS046
GWNGK734	GWNGL668	GWNGN176	GWNGN872	GWNGP239	GWNGS047
GWNGK735	GWNGL669	GWNGN177	GWNGN873	GWNGP240	GWNGS048
GWNGK736	GWNGL670	GWNGN195	GWNGN874	GWNGP241	GWNGS049
GWNGK737	GWNGL671	GWNGN196	GWNGN875	GWNGP242	GWNGS050
GWNGK738	GWNGL672	GWNGN197	GWNGN876	GWNGP243	GWNGS051
GWNGK739	GWNGL826	GWNGN198	GWNGN877	GWNGP244	GWNGS052
GWNGK994	GWNGL827	GWNGN199	GWNGN878	GWNGP245	GWNGS095
GWNGK995	GWNGL828	GWNGN200	GWNGN879	GWNGP246	GWNGS096
GWNGK996	GWNGL829	GWNGN201	GWNGN880	GWNGP247	GWNGS097
GWNGK997	GWNGL830	GWNGN237	GWNGN881	GWNGP248	GWNGS098
GWNGK998	GWNGL936	GWNGN239	GWNGN882	GWNGP249	GWNGS099
GWNGL001	GWNGL937	GWNGN240	GWNGN883	GWNGP250	GWNGS100
GWNGL002	GWNGL938	GWNGN241	GWNGN885	GWNGP251	GWNGS101
GWNGL003	GWNGL939	GWNGN243	GWNGN886	GWNGP252	GWNGS102
GWNGL004	GWNGL940	GWNGN244	GWNGN887	GWNGP253	GWNGS103
GWNGL005	GWNGL941	GWNGN245	GWNGN888	GWNGP254	GWNGS104
GWNGL006	GWNGL942	GWNGN246	GWNGN889	GWNGP255	GWNGS105
GWNGL007	GWNGM058	GWNGN248	GWNGN890	GWNGP256	GWNGS106
GWNGL008	GWNGM059	GWNGN456	GWNGN891	GWNGP257	GWNGS107
GWNGL009	GWNGM060	GWNGN812	GWNGN892	GWNGP258	GWNGS108
GWNGL269	GWNGM061	GWNGN813	GWNGN893	GWNGP678	GWNGS109
GWNGL270	GWNGM062	GWNGN814	GWNGN898	GWNGP930	GWNGS110
GWNGL271	GWNGM063	GWNGN815	GWNGN900	GWNGP931	GWNGS111
GWNGL272	GWNGM148	GWNGN816	GWNGN901	GWNGP932	GWNGS112
GWNGL273	GWNGM204	GWNGN817	GWNGN902	GWNGP933	GWNGS113
GWNGL274	GWNGM205	GWNGN818	GWNGP087	GWNGP934	GWNGS114
GWNGL275	GWNGM206	GWNGN819	GWNGP089	GWNGP935	GWNGS115
GWNGL276	GWNGM207	GWNGN820	GWNGP090	GWNGP936	GWNGS243
GWNGL277	GWNGM208	GWNGN821	GWNGP091	GWNGP937	GWNGS244
GWNGL278	GWNGM209	GWNGN831	GWNGP092	GWNGP938	GWNGS245
GWNGL350	GWNGM354	GWNGN832	GWNGP093	GWNGP939	GWNGS247
GWNGL351	GWNGM355	GWNGN833	GWNGP094	GWNGP940	GWNGS249
GWNGL352	GWNGM356	GWNGN834	GWNGP095	GWNGP941	GWNGS250
GWNGL353	GWNGM358	GWNGN835	GWNGP096	GWNGP943	GWNGS251



## Appendix 2 – P/N 1795M36P02 – Affected Serial Numbers

GWNGS252	GWNGS621	GWNGS984	GWNGT370	GWNGT609	GWNSA017
GWNGS253	GWNGS622	GWNGS985	GWNGT371	GWNGT610	GWNSA018
GWNGS254	GWNGS623	GWNGS986	GWNGT372	GWNGT611	GWNSA019
GWNGS391	GWNGS624	GWNGS987	GWNGT373	GWNGT612	GWNSA020
GWNGS392	GWNGS625	GWNGS988	GWNGT374	GWNGT613	GWNSA021
GWNGS393	GWNGS626	GWNGS989	GWNGT375	GWNGT614	GWNSA022
GWNGS394	GWNGS627	GWNGS990	GWNGT434	GWNGT615	GWNSA023
GWNGS395	GWNGS628	GWNGT018	GWNGT435	GWNGT616	GWNSA024
GWNGS396	GWNGS629	GWNGT019	GWNGT436	GWNGT617	GWNSA026
GWNGS397	GWNGS677	GWNGT085	GWNGT437	GWNGT618	GWNSA027
GWNGS398	GWNGS678	GWNGT086	GWNGT438	GWNGT619	GWNSA028
GWNGS417	GWNGS679	GWNGT087	GWNGT439	GWNGT620	GWNSA029
GWNGS418	GWNGS680	GWNGT088	GWNGT441	GWNGT664	GWNSA030
GWNGS419	GWNGS681	GWNGT089	GWNGT442	GWNGT665	GWNSA031
GWNGS420	GWNGS682	GWNGT090	GWNGT445	GWNGT666	GWNSA032
GWNGS421	GWNGS683	GWNGT091	GWNGT446	GWNGT667	GWNSA033
GWNGS422	GWNGS684	GWNGT092	GWNGT447	GWNGT668	GWNSA034
GWNGS423	GWNGS685	GWNGT130	GWNGT512	GWNGT669	GWNSA036
GWNGS424	GWNGS686	GWNGT198	GWNGT513	GWNGT670	GWNSA037
GWNGS435	GWNGS743	GWNGT199	GWNGT514	GWNGT671	GWNSA038
GWNGS450	GWNGS744	GWNGT200	GWNGT515	GWNGT672	GWNSA039
GWNGS451	GWNGS745	GWNGT201	GWNGT516	GWNGT673	GWNSA081
GWNGS452	GWNGS746	GWNGT202	GWNGT517	GWNGT674	GWNSA082
GWNGS453	GWNGS747	GWNGT203	GWNGT518	GWNGT675	GWNSA083
GWNGS454	GWNGS748	GWNGT205	GWNGT519	GWNGT676	GWNSA084
GWNGS455	GWNGS751	GWNGT206	GWNGT520	GWNGT677	GWNSA085
GWNGS456	GWNGS771	GWNGT207	GWNGT521	GWNGT775	GWNSA086
GWNGS457	GWNGS819	GWNGT208	GWNGT522	GWNGT776	GWNSA087
GWNGS458	GWNGS820	GWNGT209	GWNGT523	GWNGT777	GWNSA088
GWNGS533	GWNGS821	GWNGT210	GWNGT554	GWNGT778	GWNSA089
GWNGS534	GWNGS822	GWNGT211	GWNGT555	GWNGT779	GWNSA090
GWNGS535	GWNGS823	GWNGT212	GWNGT556	GWNGT780	GWNSA091
GWNGS536	GWNGS824	GWNGT213	GWNGT557	GWNGT781	GWNSA092
GWNGS537	GWNGS825	GWNGT283	GWNGT558	GWNGT782	GWNSA093
GWNGS538	GWNGS826	GWNGT284	GWNGT559	GWNGT783	GWNSA094
GWNGS539	GWNGS827	GWNGT285	GWNGT560	GWNGT784	GWNSA095
GWNGS540	GWNGS974	GWNGT286	GWNGT561	GWNGT785	GWNSA096
GWNGS541	GWNGS975	GWNGT287	GWNGT562	GWNGT786	GWNSA097
GWNGS542	GWNGS976	GWNGT288	GWNGT563	GWNGT787	GWNSA098
GWNGS543	GWNGS977	GWNGT289	GWNGT564	GWNGT788	GWNSA099
GWNGS544	GWNGS978	GWNGT290	GWNGT565	GWNSA011	GWNSA100
GWNGS545	GWNGS979	GWNGT291	GWNGT566	GWNSA012	GWNSA101
GWNGS547	GWNGS980	GWNGT366	GWNGT591	GWNSA013	GWNSA102
GWNGS548	GWNGS981	GWNGT367	GWNGT606	GWNSA014	GWNSA103
GWNGS549	GWNGS982	GWNGT368	GWNGT607	GWNSA015	GWNSA104
GWNGS550	GWNGS983	GWNGT369	GWNGT608	GWNSA016	GWNSA105



## Appendix 2 – P/N 1795M36P02 – Affected Serial Numbers

GWNSA106	GWNSA628	GWNSA867	GWNSB143	GWNSB434	GWNSB704
GWNSA107	GWNSA629	GWNSA868	GWNSB144	GWNSB435	GWNSB705
GWNSA108	GWNSA630	GWNSA869	GWNSB145	GWNSB436	GWNSB706
GWNSA109	GWNSA631	GWNSA870	GWNSB146	GWNSB437	GWNSB707
GWNSA110	GWNSA632	GWNSA871	GWNSB147	GWNSB438	GWNSB708
GWNSA111	GWNSA633	GWNSA872	GWNSB148	GWNSB439	GWNSB709
GWNSA114	GWNSA634	GWNSA873	GWNSB149	GWNSB440	GWNSB710
GWNSA115	GWNSA635	GWNSA874	GWNSB150	GWNSB441	GWNSB711
GWNSA116	GWNSA636	GWNSA875	GWNSB151	GWNSB442	GWNSB712
GWNSA117	GWNSA637	GWNSA877	GWNSB152	GWNSB443	GWNSB713
GWNSA118	GWNSA638	GWNSA878	GWNSB153	GWNSB444	GWNSB714
GWNSA515	GWNSA639	GWNSA879	GWNSB154	GWNSB518	GWNSB715
GWNSA516	GWNSA640	GWNSA880	GWNSB155	GWNSB519	GWNSB716
GWNSA517	GWNSA641	GWNSA881	GWNSB156	GWNSB520	GWNSB717
GWNSA518	GWNSA642	GWNSA882	GWNSB157	GWNSB521	GWNSB760
GWNSA519	GWNSA644	GWNSA883	GWNSB158	GWNSB522	GWNSB761
GWNSA520	GWNSA645	GWNSB003	GWNSB159	GWNSB523	GWNSB762
GWNSA521	GWNSA646	GWNSB004	GWNSB305	GWNSB524	GWNSB763
GWNSA522	GWNSA647	GWNSB005	GWNSB306	GWNSB525	GWNSB764
GWNSA523	GWNSA648	GWNSB006	GWNSB307	GWNSB526	GWNSB765
GWNSA524	GWNSA750	GWNSB007	GWNSB308	GWNSB527	GWNSB766
GWNSA525	GWNSA751	GWNSB008	GWNSB309	GWNSB528	GWNSB767
GWNSA526	GWNSA752	GWNSB009	GWNSB310	GWNSB529	GWNSB768
GWNSA527	GWNSA753	GWNSB010	GWNSB311	GWNSB530	GWNSB769
GWNSA528	GWNSA754	GWNSB011	GWNSB312	GWNSB531	GWNSB770
GWNSA530	GWNSA755	GWNSB012	GWNSB313	GWNSB532	GWNSB771
GWNSA531	GWNSA757	GWNSB122	GWNSB314	GWNSB533	GWNSB772
GWNSA532	GWNSA847	GWNSB123	GWNSB315	GWNSB534	GWNSB773
GWNSA533	GWNSA848	GWNSB124	GWNSB316	GWNSB535	GWNSB774
GWNSA534	GWNSA849	GWNSB125	GWNSB317	GWNSB537	GWNSB775
GWNSA535	GWNSA850	GWNSB126	GWNSB318	GWNSB538	GWNSB776
GWNSA537	GWNSA851	GWNSB127	GWNSB319	GWNSB570	GWNSB777
GWNSA538	GWNSA852	GWNSB128	GWNSB320	GWNSB571	GWNSB778
GWNSA539	GWNSA853	GWNSB129	GWNSB321	GWNSB572	GWNSB779
GWNSA540	GWNSA854	GWNSB130	GWNSB322	GWNSB573	GWNSB852
GWNSA541	GWNSA855	GWNSB131	GWNSB323	GWNSB574	GWNSB853
GWNSA542	GWNSA856	GWNSB132	GWNSB324	GWNSB575	GWNSB854
GWNSA543	GWNSA857	GWNSB133	GWNSB424	GWNSB576	GWNSB855
GWNSA544	GWNSA858	GWNSB134	GWNSB425	GWNSB628	GWNSB857
GWNSA545	GWNSA859	GWNSB135	GWNSB426	GWNSB629	GWNSB858
GWNSA546	GWNSA860	GWNSB136	GWNSB427	GWNSB698	GWNSB859
GWNSA623	GWNSA862	GWNSB137	GWNSB428	GWNSB699	GWNSB860
GWNSA624	GWNSA863	GWNSB138	GWNSB430	GWNSB700	GWNSB861
GWNSA625	GWNSA864	GWNSB139	GWNSB431	GWNSB701	GWNSB862
GWNSA626	GWNSA865	GWNSB140	GWNSB432	GWNSB702	GWNSB863
GWNSA627	GWNSA866	GWNSB141	GWNSB433	GWNSB703	GWNSB864



## Appendix 2 – P/N 1795M36P02 – Affected Serial Numbers

GWNSB865	GWNSC077	GWNSC262	GWNSC454	GWNSC573	GWNSC850
GWNSB866	GWNSC078	GWNSC263	GWNSC455	GWNSC574	GWNSC851
GWNSB867	GWNSC079	GWNSC264	GWNSC456	GWNSC575	GWNSC852
GWNSB868	GWNSC080	GWNSC265	GWNSC457	GWNSC576	GWNSC853
GWNSB869	GWNSC081	GWNSC266	GWNSC458	GWNSC577	GWNSC854
GWNSB870	GWNSC082	GWNSC267	GWNSC459	GWNSC578	GWNSC870
GWNSB871	GWNSC083	GWNSC268	GWNSC460	GWNSC579	GWNSC871
GWNSB872	GWNSC084	GWNSC269	GWNSC461	GWNSC580	GWNSC926
GWNSB910	GWNSC085	GWNSC271	GWNSC462	GWNSC581	GWNSC927
GWNSB911	GWNSC086	GWNSC344	GWNSC463	GWNSC626	GWNSC928
GWNSB932	GWNSC087	GWNSC345	GWNSC464	GWNSC627	GWNSC929
GWNSB933	GWNSC088	GWNSC346	GWNSC465	GWNSC628	GWNSC930
GWNSB934	GWNSC089	GWNSC347	GWNSC466	GWNSC629	GWNSC931
GWNSB935	GWNSC090	GWNSC348	GWNSC467	GWNSC630	GWNSC932
GWNSB936	GWNSC091	GWNSC349	GWNSC468	GWNSC631	GWNSC933
GWNSB937	GWNSC093	GWNSC350	GWNSC469	GWNSC632	GWNSC934
GWNSB938	GWNSC094	GWNSC351	GWNSC470	GWNSC633	GWNSC935
GWNSB939	GWNSC095	GWNSC353	GWNSC471	GWNSC634	GWNSC936
GWNSB941	GWNSC096	GWNSC354	GWNSC502	GWNSC635	GWNSC937
GWNSB943	GWNSC097	GWNSC356	GWNSC503	GWNSC709	GWNSC938
GWNSB945	GWNSC233	GWNSC357	GWNSC504	GWNSC710	GWNSC939
GWNSB946	GWNSC234	GWNSC358	GWNSC505	GWNSC711	GWNSC940
GWNSB947	GWNSC235	GWNSC359	GWNSC506	GWNSC712	GWNSC941
GWNSB948	GWNSC236	GWNSC360	GWNSC507	GWNSC713	GWNSC942
GWNSB949	GWNSC237	GWNSC361	GWNSC508	GWNSC714	GWNSC943
GWNSB950	GWNSC238	GWNSC362	GWNSC509	GWNSC715	GWNSC945
GWNSB951	GWNSC240	GWNSC363	GWNSC510	GWNSC716	GWNSC946
GWNSC058	GWNSC241	GWNSC435	GWNSC511	GWNSC717	GWNSC947
GWNSC059	GWNSC242	GWNSC436	GWNSC512	GWNSC718	GWNSC948
GWNSC060	GWNSC243	GWNSC437	GWNSC513	GWNSC719	GWNSC949
GWNSC061	GWNSC244	GWNSC438	GWNSC514	GWNSC720	GWNSC950
GWNSC062	GWNSC245	GWNSC439	GWNSC515	GWNSC721	GWNSC951
GWNSC063	GWNSC246	GWNSC440	GWNSC516	GWNSC836	GWNSC952
GWNSC064	GWNSC247	GWNSC441	GWNSC517	GWNSC837	GWNSC953
GWNSC065	GWNSC248	GWNSC442	GWNSC518	GWNSC838	GWNSC954
GWNSC066	GWNSC249	GWNSC443	GWNSC561	GWNSC839	GWNSD209
GWNSC067	GWNSC250	GWNSC444	GWNSC562	GWNSC840	GWNSD210
GWNSC068	GWNSC252	GWNSC445	GWNSC563	GWNSC841	GWNSD211
GWNSC069	GWNSC253	GWNSC446	GWNSC564	GWNSC842	GWNSD212
GWNSC070	GWNSC254	GWNSC447	GWNSC565	GWNSC843	GWNSD213
GWNSC071	GWNSC256	GWNSC448	GWNSC566	GWNSC844	GWNSD214
GWNSC072	GWNSC257	GWNSC449	GWNSC567	GWNSC845	GWNSD215
GWNSC073	GWNSC258	GWNSC450	GWNSC568	GWNSC846	GWNSD216
GWNSC074	GWNSC259	GWNSC451	GWNSC569	GWNSC847	GWNSD217
GWNSC075	GWNSC260	GWNSC452	GWNSC570	GWNSC848	GWNSD218
GWNSC076	GWNSC261	GWNSC453	GWNSC571	GWNSC849	GWNSD219



## Appendix 2 – P/N 1795M36P02 – Affected Serial Numbers

GWNSD220	GWNSD290	GWNSD525	GWNSD957	GWNSE005	GWNSE314
GWNSD221	GWNSD291	GWNSD526	GWNSD958	GWNSE006	GWNSE315
GWNSD222	GWNSD309	GWNSD527	GWNSD959	GWNSE136	GWNSE316
GWNSD223	GWNSD310	GWNSD528	GWNSD960	GWNSE137	GWNSE317
GWNSD224	GWNSD311	GWNSD529	GWNSD961	GWNSE138	GWNSE318
GWNSD225	GWNSD312	GWNSD530	GWNSD962	GWNSE139	GWNSE319
GWNSD226	GWNSD313	GWNSD531	GWNSD963	GWNSE140	GWNSE320
GWNSD227	GWNSD314	GWNSD532	GWNSD964	GWNSE141	GWNSE321
GWNSD228	GWNSD315	GWNSD533	GWNSD965	GWNSE142	GWNSE322
GWNSD229	GWNSD316	GWNSD534	GWNSD966	GWNSE143	GWNSE323
GWNSD230	GWNSD317	GWNSD535	GWNSD967	GWNSE144	GWNSE324
GWNSD231	GWNSD318	GWNSD536	GWNSD968	GWNSE145	GWNSE325
GWNSD233	GWNSD319	GWNSD537	GWNSD969	GWNSE146	GWNSE326
GWNSD234	GWNSD320	GWNSD538	GWNSD970	GWNSE147	GWNSE327
GWNSD257	GWNSD321	GWNSD741	GWNSD971	GWNSE148	GWNSE328
GWNSD258	GWNSD322	GWNSD742	GWNSD972	GWNSE149	GWNSE329
GWNSD259	GWNSD323	GWNSD743	GWNSD973	GWNSE150	GWNSE330
GWNSD260	GWNSD324	GWNSD744	GWNSD974	GWNSE151	GWNSE395
GWNSD261	GWNSD343	GWNSD745	GWNSD975	GWNSE152	GWNSE419
GWNSD262	GWNSD344	GWNSD746	GWNSD976	GWNSE284	GWNSE420
GWNSD263	GWNSD346	GWNSD747	GWNSD977	GWNSE285	GWNSE421
GWNSD264	GWNSD490	GWNSD748	GWNSD978	GWNSE286	GWNSE422
GWNSD265	GWNSD491	GWNSD749	GWNSD979	GWNSE287	GWNSE423
GWNSD266	GWNSD492	GWNSD750	GWNSD980	GWNSE288	GWNSE424
GWNSD267	GWNSD494	GWNSD751	GWNSD981	GWNSE289	GWNSE425
GWNSD268	GWNSD495	GWNSD752	GWNSD982	GWNSE290	GWNSE426
GWNSD269	GWNSD496	GWNSD753	GWNSD983	GWNSE291	GWNSE427
GWNSD270	GWNSD497	GWNSD755	GWNSD984	GWNSE292	GWNSE428
GWNSD271	GWNSD498	GWNSD756	GWNSD985	GWNSE294	GWNSE429
GWNSD272	GWNSD499	GWNSD757	GWNSD986	GWNSE295	GWNSE430
GWNSD273	GWNSD500	GWNSD758	GWNSD987	GWNSE296	GWNSE431
GWNSD274	GWNSD501	GWNSD759	GWNSD988	GWNSE297	GWNSE432
GWNSD276	GWNSD502	GWNSD760	GWNSD989	GWNSE298	GWNSE433
GWNSD277	GWNSD503	GWNSD761	GWNSD990	GWNSE299	GWNSE434
GWNSD278	GWNSD504	GWNSD770	GWNSD991	GWNSE300	GWNSE435
GWNSD279	GWNSD505	GWNSD946	GWNSD992	GWNSE301	GWNSE436
GWNSD280	GWNSD506	GWNSD947	GWNSD993	GWNSE302	GWNSE437
GWNSD281	GWNSD507	GWNSD948	GWNSD994	GWNSE303	GWNSE438
GWNSD282	GWNSD508	GWNSD949	GWNSD995	GWNSE304	GWNSE439
GWNSD283	GWNSD509	GWNSD950	GWNSD996	GWNSE305	GWNSE440
GWNSD284	GWNSD519	GWNSD951	GWNSD997	GWNSE306	GWNSE443
GWNSD285	GWNSD520	GWNSD952	GWNSD998	GWNSE307	GWNSE445
GWNSD286	GWNSD521	GWNSD953	GWNSE001	GWNSE308	GWNSE446
GWNSD287	GWNSD522	GWNSD954	GWNSE002	GWNSE309	GWNSE447
GWNSD288	GWNSD523	GWNSD955	GWNSE003	GWNSE310	GWNSE448
GWNSD289	GWNSD524	GWNSD956	GWNSE004	GWNSE312	GWNSE449



## Appendix 2 – P/N 1795M36P02 – Affected Serial Numbers

GWNSE450	GWNSE543	GWNSE759	GWNSE781	GWNSE931	GWNSE953
GWNSE522	GWNSE544	GWNSE760	GWNSE782	GWNSE932	GWNSE954
GWNSE523	GWNSE545	GWNSE761	GWNSE783	GWNSE933	GWNSE955
GWNSE524	GWNSE546	GWNSE762	GWNSE784	GWNSE934	GWNSE956
GWNSE525	GWNSE547	GWNSE763	GWNSE785	GWNSE935	GWNSE957
GWNSE526	GWNSE548	GWNSE764	GWNSE786	GWNSE936	GWNSE958
GWNSE527	GWNSE549	GWNSE765	GWNSE787	GWNSE937	GWNSE959
GWNSE528	GWNSE550	GWNSE766	GWNSE788	GWNSE938	GWNSE960
GWNSE529	GWNSE551	GWNSE767	GWNSE887	GWNSE939	GWNSE961
GWNSE530	GWNSE552	GWNSE768	GWNSE888	GWNSE940	GWNSE962
GWNSE531	GWNSE553	GWNSE769	GWNSE889	GWNSE941	GWNSE963
GWNSE532	GWNSE554	GWNSE770	GWNSE890	GWNSE942	GWNSE964
GWNSE533	GWNSE555	GWNSE771	GWNSE891	GWNSE943	GWNSE965
GWNSE534	GWNSE750	GWNSE772	GWNSE892	GWNSE944	GWNSE966
GWNSE535	GWNSE751	GWNSE773	GWNSE893	GWNSE945	GWNSE967
GWNSE536	GWNSE752	GWNSE774	GWNSE894	GWNSE946	GWNSE968
GWNSE537	GWNSE753	GWNSE775	GWNSE896	GWNSE947	GWNSE969
GWNSE538	GWNSE754	GWNSE776	GWNSE897	GWNSE948	
GWNSE539	GWNSE755	GWNSE777	GWNSE898	GWNSE949	
GWNSE540	GWNSE756	GWNSE778	GWNSE899	GWNSE950	
GWNSE541	GWNSE757	GWNSE779	GWNSE929	GWNSE951	
GWNSE542	GWNSE758	GWNSE780	GWNSE930	GWNSE952	

